

FACTORY STANDARD EQUIPMENT**POWERTRAIN/SUSPENSION**

AR2	Axle ratio 3.923
C38	Rear springs for 3.88-t weight variant
C42	Rear axle stabilizer, under frame
C45	Front axle stabilizer, reinforced
C47	Shock absorbers, reinforced
CF2	Suspension w/Frt and Rr Stabilizer
G40	5-speed automatic transmission (W5A 380)
K60	Straight rear-exiting exhaust
KB0	100-litre fuel tank
KL1	Auxiliary heater fuel sending unit
KL5	Fuel filter with water separator
KP0	Bodywork SCR
MG5	3.0L V6 BlueTEC Diesel (OM 642 -188hp/325lb-ft)
MH1	EPA10 Compliant low-emission engine
XL8	GVWR 3,880 kg (8,550 lbs)

ELECTRONIC SYSTEMS

E30	Battery quick-disconnect
E40	Trailer hitch prep package, 7-pole
ED8	Electrical pre-installation for PSM
EE8	Battery, high capacity 100 Ah/760 CCA
EK1	Body builder connector under driver's seat
ES0	Jump start terminal
M46	Alternator 14 V/220 A

INTERIOR

CL1	Steering wheel w/ height and reach adjustment
D93	Deletion of partition
E46	12 V Power outlet in driver's seat base
EL8	Five speakers in cabin
EN0	Sound 5 with AM/FM, single-disc CD, MP3
F61	Rearview mirror
F66	Lockable glove compartment
FF5	Shelf above windshield
FJ1	Hinged lid for center console storage compartment
HH2	Electric heater booster
HH9	Air conditioning, front compartment
HZ9	Diesel heater booster - 5kW
J10	Speedometer, km/h
J65	Outside temperature display
L65	Interior lights, cargo/passenger compartment
S04	Adjustable passenger's seat
S22	Armrest for driver's seat
S25	Armrest for front passenger's seat
T74	Assist handle at sliding door on B-pillar
T85	Assist handle, left rear door
T86	Assist handle, right rear door
V43	Wood floor
V85	Smoker's package, front console
VH5	LIMA Cloth seats

EXTERIOR

F68	Heated and power adjustable side mirrors
H21	Heat-insulating glass with windshield band
L05	Automatic daytime running lights
L94	Deletion of parking lamps
LB5	LED brake light
MZ0	BlueEFFICIENCY badge
P47	Front mud flaps
P48	Rear mud flaps
O67	Tow hook, rear
R65	Spare wheel bracket below frame end
R87	Spare wheel
RF1	Tire brand, Continental
RH8	Tires - LT 245/75 R 16
RM0	All-season tires
RM9	Tire brand, special request
RS3	Steel wheels 6.5J x 16
RW4	Deletion of tire sealant kit
T09	Sliding door with extended track
T12	Two stage opening for sliding door
T16	Sliding door, passenger side
W54	Rear doors, double wing, 270 degree opening

SAFETY/CONVENIENCE

BB3	Electronic Stability Program (ESP)
E07	Hill-start assist
F11	Keyless Entry
F13	Tire pressure monitoring
J58	Seat belt warning for driver's seat
RY2	Front and rear wireless tire pressure monitoring system
SA5	Front airbag, driver
SA6	Front airbag, passenger
Y43	Hydraulic jack

OTHER

IG3	Tracking Code
XC8	VIN visible from outside
XS7	Labels/publications printed in English/French
XY2	Model year 2012
Z44	NAFTA vehicle registration
Z65	Packing for sea transport
ZU7	National version for Canada
ZZ4	Mercedes-Benz specification

Sprinter 2500 Cargo 144"

MY12

Ordering Designation: 25C144 Baumuster: 906 633 13

Last updated: July 12, 2011

VEHICLE PRICING & OPTIONS

Prices are valid on date of delivery. Prices, design & equipment are subject to change without notice

	MSRP
Sprinter 2500 Cargo 144"	\$42,900

OPTIONAL PACKAGES

CODE	DESCRIPTION	MSRP
VPP	Convenience Package	\$500
CL4	Multifunction steering wheel w/ trip computer	
FZ9	Two additional master keys	
JK3	Instrument cluster with pixel-matrix display	
MS1	Cruise control	
VLP	Interior Lighting Package	\$300
	<i>replaces L65; not with VIP/D56/H08</i>	
L63	Ceiling lamp in cargo compartment	
LD0	Overhead control panel with 2 reading lamps	
VXP	Bi-xenon Headlamp Package	\$1,100
F46	Headlamp washing system	
L16	Halogen fog lamps	
LG1	Bi-xenon headlamps with cornering function	
VCP	Heated Seat Package	\$350
	<i>not with D64</i>	
H15	Heated front passenger's seat	
H16	Heated driver's seat	
VVP	Crew Van Package	\$2,200
	<i>not with S23/VBP/VFP/VHP/VIP/VMP; replaces V43</i>	
H00	Warm/cool air duct to passenger compartment	
SD0	ISOFIX child seat attachment points	
U62	3-seater bench, first row, narrow	
V25	Interior trim, hardboard, half height	
V39	Weight optimized plastic floor	
V40	Crew cab floor assembly	
V46	Rubber floor mat in rear	
W16	Fixed window, front left in sidewall/sliding door	
W17	Fixed window, front right in sidewall/sliding door	
VBP	Basic Window Package	\$650
	<i>not with W78/VFP/VVP/VIP</i>	
H22	Rear window defroster	
VA7	Storage compartment with net, rear doors	
W17	Fixed window, front right in sidewall/sliding door	
W61	Fixed window, rear doors	
W70	Privacy glass	
VFP	Full Window Package	\$1,000
	<i>not with W78/VA3/VVP/VEP/VBP/VHP</i>	
H22	Rear window defroster	
VA7	Storage compartment with net, rear doors	
W02	Full window package	
W16	Fixed window, front left in sidewall/sliding door	
W17	Fixed window, front right in sidewall/sliding door	
W27	Fixed window, rear left	
W28	Fixed window, rear right	
W61	Fixed window, rear doors	

Sprinter 2500 Cargo 144"

MY12

Ordering Designation: 25C144 Baumuster: 906 633 13

Last updated: July 12, 2011

OPTIONAL PACKAGES (Continued)

CODE	DESCRIPTION	MSRP
VEP	Extended Cargo Package	\$700
	<i>not with D64/VVP/VFP/VIP/V46</i>	
V42	Sidewall lashing rails on waist rail	
VC4	Cargo lashing rails, upper	
VV2	Load securing rail system	
YK3	Tensioning straps	
YK4	Lashing rail straps	
VMP	Mobility Prep. Package	\$790
	<i>replaces ED8; not with VVP</i>	
E28	Additional battery for retrofit	
E36	Cutoff relay for additional battery	
ED5	Programmable Special Module (PSM)	
ES2	12 V Power outlet in rear compartment	
H00	Warm/cool air duct to passenger compartment	
VGP	Comfort Seat Package	\$390
	<i>replaces S04; not with S23/VSP/VAP</i>	
SB1	Comfort driver's seat	
SB2	Comfort passenger's seat	
VSP	Swivel Seat Package	\$950
	<i>replaces S04; not with D64/S23/VAP/VGP</i>	
BE2	Folding handbrake lever	
S87	Driver's seat frame, low	
S88	Passenger's seat frame, low	
SB1	Comfort driver's seat	
SB2	Comfort passenger's seat	
SD2	Belt mounting point for deleted driver/passenger seat	
SR8	Swivel base for driver's seat	
SR9	Swivel base for passenger's seat	
VAP	Suspension Seat Package	\$820
	<i>replaces S04; not with D64/S23/VSP/VGP</i>	
S87	Driver's seat frame, low	
S88	Passenger's seat frame, low	
SB3	Suspension seat, comfort version, driver's seat	
SB4	Suspension seat, comfort version, passenger's seat	
VHP	Rear Heating Package (Cargo)	\$1,400
	<i>not with D64/V25/VIP/VFP/VVP</i>	
H01	Additional insulation for rear compartment	
H04	Additional insulation for front compartment	<i>note: if VHP is ordered on a vehicle with D50/D51/D53, V07 must be added from individual options</i>
H13	Additional heat exchanger	
VA3	Interior trim, washable, full height	
VIP	Luxury Interior Package	\$2,400
	<i>must have VFP; not with VA1/VA3/V25/VLP/VVP/VEP/VHP</i>	
H01	Additional insulation for rear compartment	
H04	Additional insulation for front compartment	
LD0	Overhead control panel with 2 reading lamps	
LD4	Convenience lighting in cargo/passenger compartment	
V21	Interior trim, luxury	
V31	Window pillar trim	
V36	Roof trim	
V64	Ashtrays, rear	

Sprinter 2500 Cargo 144"

MY12

Ordering Designation: 25C144 Baumuster: 906 633 13

Last updated: July 12, 2011

OPTIONAL EQUIPMENT

CODE	DESCRIPTION	MSRP
AR3	Axle ratio 4.182 <i>replaces AR2</i>	\$0
C39	Rear springs for 3.88-t weight variant, comfort <i>replaces C38</i>	\$150
CF4	Suspension w/ H.D. Frt and Rr Stabilizers <i>replaces CF2+C47</i>	\$140
CT1	Vibration damper	\$140
D03	High roof	\$2,500
D13	Mounting rails for roof rack	\$250
D22	Fixed rear sunroof <i>not with VIP/D56/H72</i>	\$400
D50	Full partition <i>replaces D93+T74; not with D51/D53/D62/D64/VVP/VMP</i>	\$270
	<i>includes: T77 Assist handle at sliding door on partition</i>	
D51	Full partition with 1 window <i>replaces D93+T74; not with D50/D53/D62/D64/VVP/VMP</i>	\$310
	<i>includes: T77 Assist handle at sliding door on partition</i>	
D53	Full partition with 1 sliding window <i>replaces D93+T74; not with D50/D51/D62/D64/VVP/VMP</i>	\$490
	<i>includes: T77 Assist handle at sliding door on partition</i>	
D62	Pre-installation for partition	\$140
D64	Full partition with sliding door <i>replaces D93+T74+S04+SA6</i> <i>includes: T77 Assist handle at sliding door on partition</i> <i>S20 Folding front passenger's seat</i> <i>S99 Deletion of passenger's seat base</i> <i>note: passenger airbag is deleted</i>	\$1,700
E28	Additional battery for retrofit <i>includes: E36 Cutoff relay for additional battery</i>	\$470
ED4	AGM Battery 95 Ah/850 CCA <i>replaces EE8</i>	\$190
ED5	Programmable Special Module (PSM) <i>replaces ED8</i>	\$300
EJ3	Audio 20 with AM/FM,6-disc CD, MP3, Bluetooth <i>replaces EN0; not with ERO</i>	\$900
ERO	Pre-installation for radio <i>replaces EN0; not with EJ3</i>	-\$300
ES2	12 V Power outlet in rear compartment	\$70
EZ8	PARKTRONIC	\$940
F49	Heated windshield <i>must have JA5+(VLP/VIP)</i>	\$330
FF8	Storage slot at front under roof liner - 1 DIN	\$100
FK3	Chrome grille	\$250
FR7	Rear view camera wiring prep <i>not with FR8</i>	\$80
FR8	Rear view camera <i>replaces FJ1; not with FR7</i>	\$900
FY1	Security alarm with interior motion sensor <i>must have VLP</i>	\$490
FZ9	Two additional master keys	\$140
H00	Warm/cool air duct to passenger compartment <i>not with D50/D51/D53/D64/S99</i>	\$80
H01	Additional insulation for rear compartment <i>must have V25/VA1/VA3</i>	\$140
H04	Additional insulation for front compartment <i>if ordered with D50/D51/D53 then must have V07</i>	\$140
H08	High-output A/C system in passenger compartment <i>includes: V36 Roof trim</i> <i>must have ED4; not with VEP/VIP/VLP/VA3/D05/D22</i>	\$2,900
H12	Heater, auxiliary front 5 kW <i>replaces HZ9; not with HZ5</i>	\$250
H13	Additional heat exchanger <i>not with D64/H88/T19/T93/VC5/VVP</i>	\$940
H16	Heated driver's seat <i>not with VCP</i>	\$210
H72	Electric roof fan <i>not with D22/H08/VIP</i>	\$480
H91	Deletion of Air-conditioning system <i>replaces HH9; not with H08</i>	-\$730
HZ5	Additional warm water heating with timer 10 kw <i>replaces HZ9; must have H13; not with H12/T19</i>	\$1,200
JA5	Automatic headlamps and windshield wipers <i>must have VLP/VIP</i>	\$410
JW0	Reverse warning system <i>not with FR8</i>	\$100

Sprinter 2500 Cargo 144"

MY12

Ordering Designation: 25C144 Baumuster: 906 633 13

Last updated: July 12, 2011

OPTIONAL EQUIPMENT (Continued)

CODE	DESCRIPTION	MSRP
L16	Halogen fog lamps	\$210
LB9	Illuminated exits	\$130
M53	High idle preset <i>includes: ED5 Programmable Special Module (PSM)</i>	not with MT4 \$650
MD3	Speed limiter - 120 km/h	\$70
MS1	Cruise control	\$390
MT4	High idle - driver adjustable <i>includes: ED5 Programmable Special Module (PSM)</i>	not with M53 \$680
N62	Pulley for additional alternator	not with N63/H08 \$440
N63	Pulley for additional compressor	not with N62/H08 \$440
Q24	Cross member with 5,000lbs towing capacity	\$250
R91	Deletion of spare wheel	replaces R87; must have R92+RR7 -\$160
R92	Deletion of spare wheel bracket	replaces R65; must have R91 \$0
RL5	Light-alloy wheels 6.5 J x 16	replaces RS3 \$920
RM1	Winter tires	replaces RM0 \$140
RR7	Tire sealant kit with electric compressor	replaces RW4 \$30
S23	Twin front passenger seats <i>includes: S78 Assist handle for inner seat</i>	replaces S04+S25; not with S20/S91/S99/SB2/VAP/VSP/VGP \$520
SB1	Comfort driver's seat	not with VAP/VGP/VSP \$220
SH6	Thorax airbag, driver	not with SH7 \$340
SH7	Thorax airbag, driver/passenger	not with D64/S23/SH6 \$480
SH9	Window airbag, driver/passenger	\$820
T19	Sliding door, driver's side	not with VHP/VIP \$890
T93	Deletion of sliding door	replaces T09+T16; not with T19/VVP \$0
V07	Rear wall lining on back of partition	must have (D50/D51/D53)+H04 \$340
V25	Interior trim, hardboard, half height	not with VA1/VA3/V21/VHP/VIP/VVP \$190
V93	Deletion of wood floor	replaces V43 -\$360
VA1	Interior trim, PVC, half height	\$410
VA3	Interior trim, washable, full height	not with V25/VIP/VFP/VVP/VHP \$460
VC5	Aluminum entrance panel, sliding door	not with H13/T19/T93/VVP/VEP/VHP \$70
VU9	Leatherette, black	replaces VH5; not with D64 \$80
W16	Fixed window, front left in sidewall/sliding door	\$180
W17	Fixed window, front right in sidewall/sliding door	\$180
W27	Fixed window, rear left	\$180
W28	Fixed window, rear right	\$180
W61	Fixed window, rear doors <i>includes: H22 Rear window defroster VA7 Storage compartment with net, rear doors</i>	\$450
W70	Privacy glass	must have Wxx/VVP/VFP \$480
W73	Step for rear wall door	not with Q24 \$180
W78	Fixed window with washer/wipers, rear doors <i>includes: H22 Rear window defroster VA7 Storage compartment with net, rear doors</i>	\$640
-	Special Paint	\$600
-	Metallic Paint	\$1,100

FACTORY STANDARD EQUIPMENT**POWERTRAIN/SUSPENSION**

AR2	Axle ratio 3.923
C38	Rear springs for 3.88-t weight variant
C40	Front axle stabilizer
C47	Shock absorbers, reinforced
G40	5-speed automatic transmission (W5A 380)
K60	Straight rear-exiting exhaust
KB0	100-litre fuel tank
KL1	Auxiliary heater fuel sending unit
KL5	Fuel filter with water separator
KP0	Bodywork SCR
MG5	3.0L V6 BlueTEC Diesel (OM 642 -188hp/325lb-ft)
MH1	EPA10 Compliant low-emission engine
XL8	GVWR 3,880 kg (8,550 lbs)

ELECTRONIC SYSTEMS

E30	Battery quick-disconnect
E40	Trailer hitch prep package, 7-pole
ED8	Electrical pre-installation for PSM
EE8	Battery, high capacity 100 Ah/760 CCA
EK1	Body builder connector under driver's seat
ES0	Jump start terminal
M46	Alternator 14 V/220 A

INTERIOR

CL1	Steering wheel w/ height and reach adjustment
D93	Deletion of partition
E46	12 V Power outlet in driver's seat base
EL8	Five speakers in cabin
EN0	Sound 5 with AM/FM, single-disc CD, MP3
F61	Rearview mirror
F66	Lockable glove compartment
FF5	Shelf above windshield
FJ1	Hinged lid for center console storage compartment
HH2	Electric heater booster
HH9	Air conditioning, front compartment
HZ9	Diesel heater booster - 5kW
J10	Speedometer, km/h
J65	Outside temperature display
L65	Interior lights, cargo/passenger compartment
S04	Adjustable passenger's seat
S22	Armrest for driver's seat
S25	Armrest for front passenger's seat
T74	Assist handle at sliding door on B-pillar
T85	Assist handle, left rear door
T86	Assist handle, right rear door
V43	Wood floor
V85	Smoker's package, front console
VH5	LIMA Cloth seats

EXTERIOR

D03	High roof
F68	Heated and power adjustable side mirrors
H21	Heat-insulating glass with windshield band
L05	Automatic daytime running lights
L94	Deletion of parking lamps
LB5	LED brake light
MZ0	BlueEFFICIENCY badge
P47	Front mud flaps
P48	Rear mud flaps
Q67	Tow hook, rear
R65	Spare wheel bracket below frame end
R87	Spare wheel
RF1	Tire brand, Continental
RH8	Tires - LT 245/75 R16
RM0	All-season tires
RM9	Tire brand, special request
RS3	Steel wheels 6.5J x 16
RW4	Deletion of tire sealant kit
T09	Sliding door with extended track
T12	Two stage opening for sliding door
T16	Sliding door, passenger side
W54	Rear doors, double wing, 270 degree opening

SAFETY/CONVENIENCE

BB3	Electronic Stability Program (ESP)
E07	Hill-start assist
FI1	Keyless Entry
FI3	Tire pressure monitoring
J58	Seat belt warning for driver's seat
RY2	Front and rear wireless tire pressure monitoring system
SA5	Front airbag, driver
SA6	Front airbag, passenger
Y43	Hydraulic jack

OTHER

IG3	Tracking Code
XC8	VIN visible from outside
XS7	Labels/publications printed in English/French
XY2	Model year 2012
Z44	NAFTA vehicle registration
Z65	Packing for sea transport
ZU7	National version for Canada
ZZ4	Mercedes-Benz specification

Sprinter 2500 Cargo 170"

MY12

Ordering Designation: 25C170 Baumuster: 906 635 13

Last updated: July 12, 2011

VEHICLE PRICING & OPTIONS

Prices are valid on date of delivery. Prices, design & equipment are subject to change without notice

	MSRP
Sprinter 2500 Cargo 170"	\$50,100

OPTIONAL PACKAGES

CODE	DESCRIPTION	MSRP
VPP	Convenience Package	\$500
CL4	Multifunction steering wheel w/ trip computer	
FZ9	Two additional master keys	
JK3	Instrument cluster with pixel-matrix display	
MS1	Cruise control	
VLP	Interior Lighting Package	\$300
	<i>replaces L65; not with VIP/D56/H08</i>	
L63	Ceiling lamp in cargo compartment	
LD0	Overhead control panel with 2 reading lamps	
VXP	Bi-xenon Headlamp Package	\$1,100
F46	Headlamp washing system	
L16	Halogen fog lamps	
LG1	Bi-xenon headlamps with cornering function	
VCP	Heated Seat Package	\$350
	<i>not with D64</i>	
H15	Heated front passenger's seat	
H16	Heated driver's seat	
VVP	Crew Van Package	\$2,200
	<i>not with S23/D05/VBP/VFP/VHP/VIP/VMP; replaces V43</i>	
H00	Warm/cool air duct to passenger compartment	
SD0	ISOFIX child seat attachment points	
U62	3-seater bench, first row, narrow	
V25	Interior trim, hardboard, half height	
V39	Weight optimized plastic floor	
V40	Crew cab floor assembly	
V46	Rubber floor mat in rear	
W16	Fixed window, front left in sidewall/sliding door	
W17	Fixed window, front right in sidewall/sliding door	
VBP	Basic Window Package	\$650
	<i>not with W78/VFP/VVP/VIP</i>	
H22	Rear window defroster	
VA7	Storage compartment with net, rear doors	
W17	Fixed window, front right in sidewall/sliding door	
W61	Fixed window, rear doors	
W70	Privacy glass	
VFP	Full Window Package	\$1,300
	<i>not with W78/VA3/VVP/VEP/VBP/VHP</i>	
H22	Rear window defroster	
VA7	Storage compartment with net, rear doors	
W02	Full window package	
W16	Fixed window, front left in sidewall/sliding door	
W17	Fixed window, front right in sidewall/sliding door	
W22	Fixed window, center left	
W23	Fixed window, center right	
W27	Fixed window, rear left	
W28	Fixed window, rear right	
W61	Fixed window, rear doors	

Sprinter 2500 Cargo 170"

MY12

Ordering Designation: 25C170 Baumuster: 906 635 13

Last updated: July 12, 2011

OPTIONAL PACKAGES (Continued)

CODE	DESCRIPTION	MSRP
VEP	Extended Cargo Package	\$700
	<i>not with D64/VVP/VFP/VIP/V46</i>	
V42	Sidewall lashing rails on waist rail	
VC4	Cargo lashing rails, upper	
VV2	Load securing rail system	
YK3	Tensioning straps	
YK4	Lashing rail straps	
VMP	Mobility Prep. Package	\$790
	<i>replaces ED8; not with VVP</i>	
E28	Additional battery for retrofit	
E36	Cutoff relay for additional battery	
ED5	Programmable Special Module (PSM)	
ES2	12 V Power outlet in rear compartment	
H00	Warm/cool air duct to passenger compartment	
VGP	Comfort Seat Package	\$390
	<i>replaces S04; not with D64/VAP/VSP</i>	
SB1	Comfort driver's seat	
SB2	Comfort passenger's seat	
VSP	Swivel Seat Package	\$950
	<i>replaces S04; not with D64/S23/VAP/VGP</i>	
BE2	Folding handbrake lever	
S87	Driver's seat frame, low	
S88	Passenger's seat frame, low	
SD2	Belt mounting point for deleted driver/passenger seat	
SR8	Swivel base for driver's seat	
SR9	Swivel base for passenger's seat	
SB1	Comfort driver's seat	
SB2	Comfort passenger's seat	
VAP	Suspension Seat Package	\$820
	<i>replaces S04; not with D64/S23/VGP/VSP</i>	
S87	Driver's seat frame, low	
S88	Passenger's seat frame, low	
SB3	Suspension seat, comfort version, driver's seat	
SB4	Suspension seat, comfort version, passenger's seat	
VHP	Rear Heating Package	\$1,400
	<i>not with D64/V25/VIP/VFP/VVP</i>	
H01	Additional insulation for rear compartment	
H04	Additional insulation for front compartment	<i>note: if VHP is ordered on a vehicle with D50/D51/D53, V07 must be added from individual options</i>
H13	Additional heat exchanger	
VA3	Interior trim, washable, full height	
VIP	Luxury Interior Package	\$2,400
	<i>must have VFP; not with VA1/VA3/V25/VLP/VVP/VEP/VHP</i>	
H01	Additional insulation for rear compartment	
H04	Additional insulation for front compartment	
LD0	Overhead control panel with 2 reading lamps	
LD4	Convenience lighting in cargo/passenger compartment	
V21	Interior trim, luxury	
V31	Window pillar trim	
V36	Roof trim	
V64	Ashtrays, rear	

Sprinter 2500 Cargo 170"

MY12

Ordering Designation: 25C170 Baumuster: 906 635 13

Last updated: July 12, 2011

OPTIONAL EQUIPMENT

CODE	DESCRIPTION	MSRP
AR3	Axle ratio 4.182 <i>replaces AR2</i>	\$0
C39	Rear springs for 3.88-t weight variant, comfort <i>replaces C38</i>	\$150
CF2	Suspension w/Frt and Rr Stabilizer <i>replaces C40; not with CF4</i> <i>includes: C42 Rear axle stabilizer, under frame</i> <i>C45 Front axle stabilizer, reinforced</i>	\$380
CF4	Suspension w/ H.D. Frt and Rr Stabilizers <i>replaces C40+C47; not with CF2</i> <i>includes: C42 Rear axle stabilizer, under frame</i> <i>C45 Front axle stabilizer, reinforced</i>	\$460
CT1	Vibration damper	\$140
D05	Super-high roof <i>must have FF4 if ordered with a partition</i> note: if vehicle is not arctic white, then code D06 must be ordered instead of D05	\$2,500
D13	Mounting rails for roof rack <i>not with D05</i>	\$250
D22	Fixed rear sunroof <i>not with VIP/D56/H72/H08</i>	\$540
D50	Full partition <i>replaces D93+T74; not with D51/D53/D62/D64/VVP/VMP</i> <i>includes: T77 Assist handle at sliding door on partition</i>	\$270
D51	Full partition with 1 window <i>replaces D93+T74; not with D50/D53/D62/D64/VVP/VMP</i> <i>includes: T77 Assist handle at sliding door on partition</i>	\$310
D53	Full partition with 1 sliding window <i>replaces D93+T74; not with D50/D51/D62/D64/S20/VVP/VMP</i> <i>includes: T77 Assist handle at sliding door on partition</i>	\$490
D62	Pre-installation for partition	\$140
D64	Full partition with sliding door <i>replaces D93+T74+S04+SA6</i> <i>not with D50/D51/D53/D62/T19/T93/VHP/VIP/VMP/VVP</i> <i>includes: T77 Assist handle at sliding door on partition</i> <i>S20 Folding front passenger's seat</i> <i>S99 Deletion of passenger's seat base</i> note: passenger airbag is deleted	\$1,700
E28	Additional battery for retrofit <i>includes: E36 Cutoff relay for additional battery</i>	\$470
ED4	AGM Battery 95 Ah/850 CCA <i>replaces EE8</i>	\$190
ED5	Programmable Special Module (PSM) <i>replaces ED8</i>	\$300
EJ3	Audio 20 with AM/FM,6-disc CD, MP3, Bluetooth <i>replaces EN0; not with ER0</i>	\$900
ER0	Pre-installation for radio <i>replaces EN0; not with EJ3</i>	-\$300
ES2	12 V Power outlet in rear compartment	\$70
EZ8	PARKTRONIC	\$940
F49	Heated windshield <i>must have JA5+(VLP/VIP)</i>	\$330
FF4	Shelf above roof trim <i>must have D05</i>	\$290
FF8	Storage slot at front under roof liner - 1 DIN	\$100
FK3	Chrome grille	\$250
FR7	Rear view camera wiring prep <i>not with FR8</i>	\$80
FR8	Rear view camera <i>replaces FJ1; not with FR7</i>	\$900
FY1	Security alarm with interior motion sensor <i>must have VLP</i>	\$490
FZ9	Two additional master keys	\$140
H00	Warm/cool air duct to passenger compartment <i>not with D50/D51/D53/D64/S99</i>	\$80
H01	Additional insulation for rear compartment <i>must have V25/VA1/VA3</i>	\$140
H04	Additional insulation for front compartment <i>if ordered with D50/D51/D53 then must have V07</i>	\$140
H08	High-output A/C system in passenger compartment <i>must have ED4; not with VEP/VIP/VLP/VA3/D05/D22</i> <i>includes: V36 Roof Trim</i>	\$2,900
H12	Heater, auxiliary front 5 kW <i>replaces HZ9; not with HZ5</i>	\$250
H13	Additional heat exchanger <i>not with D64/H88/T19/T93/VC5/VVP</i>	\$940
H16	Heated driver's seat <i>not with VCP</i>	\$210
H72	Electric roof fan <i>not with D22/H08/VIP</i>	\$480
H91	Deletion of Air-conditioning system <i>replaces HH9; not with H08</i>	-\$730
HZ5	Additional warm water heating with timer 10 kw <i>replaces HZ9; must have H13; not with H12/T19</i>	\$1,200
JA5	Automatic headlamps and windshield wipers <i>must have VLP/VIP</i>	\$410
JW0	Reverse warning system <i>not with FR8</i>	\$100

Sprinter 2500 Cargo 170"

MY12

Ordering Designation: 25C170 Baumuster: 906 635 13

Last updated: July 12, 2011

OPTIONAL EQUIPMENT (Continued)

CODE	DESCRIPTION	MSRP
L16	Halogen fog lamps	\$210
LB9	Illuminated exits	\$130
M53	High idle preset <i>includes: ED5 Programmable Special Module (PSM)</i>	not with MT4 \$650
MD3	Speed limiter - 120 km/h	\$70
MS1	Cruise control	\$390
MT4	High idle - driver adjustable <i>includes: ED5 Programmable Special Module (PSM)</i>	not with M53 \$680
N62	Pulley for additional alternator	not with N63/H08 \$440
N63	Pulley for additional compressor	not with N62/H08 \$440
Q24	Cross member with 5,000lbs towing capacity	not with W73 \$250
R91	Deletion of spare wheel	replaces R87; must have R92+RR7 -\$160
R92	Deletion of spare wheel bracket	replaces R65; must have R91 \$0
RH0	Tire brand, Kumho	replaces RF1; not with RM1 \$0
RL5	Light-alloy wheels 6.5 J x 16	replaces RS3 \$920
RM1	Winter tires	replaces RM0 \$140
RR7	Tire sealant kit with electric compressor	replaces RW4 \$30
S23	Twin front passenger seats <i>includes: S78 Assist handle for inner seat</i>	replaces S04+S25; not with S20/S91/S99/SB2/VAP/VGP/VSP \$520
SB1	Comfort driver's seat	not with VAP/VGP/VSP \$220
SH6	Thorax airbag, driver	not with SH7 \$340
SH7	Thorax airbag, driver/passenger	not with D64/S23/SH6 \$480
SH9	Window airbag, driver/passenger	\$820
T19	Sliding door, driver's side	not with VHP/VIP \$890
T93	Deletion of sliding door	replaces T09+T16; not with T19/VVP \$0
V07	Rear wall lining on back of partition	must have (D50/D51/D53)+H04 \$340
V25	Interior trim, hardboard, half height	not with VA1/VA3/V21/VHP/VIP/VVP \$190
V46	Rubber floor mat in rear	\$340
V93	Deletion of wood floor	replaces V43 -\$360
VA1	Interior trim, PVC, half height	\$410
VA3	Interior trim, washable, full height	not with V25/VIP/VFP/VVP/VHP \$460
VC5	Aluminum entrance panel, sliding door	not with H13/T19/T93/VVP/VEP/VHP \$70
VU9	Leatherette, black	replaces VH5; not with D64 \$80
W16	Fixed window, front left in sidewall/sliding door	\$180
W17	Fixed window, front right in sidewall/sliding door	\$180
W61	Fixed window, rear doors <i>includes: H22 Rear window defroster VA7 Storage compartment with net, rear doors</i>	not with VBP/VFP \$450
W70	Privacy glass	must have Wxx/VVP/VFP \$640
W73	Step for rear wall door	not with Q24 \$180
W78	Fixed window with washer/wipers, rear doors <i>includes: H22 Rear window defroster VA7 Storage compartment with net, rear doors</i>	not with W61/VBP/VFP \$640
-	Special Paint	\$600
-	Metallic Paint	\$1,100

FACTORY STANDARD EQUIPMENT**POWERTRAIN/SUSPENSION**

AR2	Axle ratio 3.923
C38	Rear springs for 3.88-t weight variant
C40	Front axle stabilizer
C47	Shock absorbers, reinforced
G40	5-speed automatic transmission (W5A 380)
K60	Straight rear-exiting exhaust
KB0	100-litre fuel tank
KL1	Auxiliary heater fuel sending unit
KL5	Fuel filter with water separator
KP0	Bodywork SCR
MG5	3.0L V6 BlueTEC Diesel (OM 642 -188hp/325lb-ft)
MH1	EPA10 Compliant low-emission engine
XL8	GVWR 3,880 kg (8,550 lbs)

ELECTRONIC SYSTEMS

E30	Battery quick-disconnect
E40	Trailer hitch prep package, 7-pole
ED8	Electrical pre-installation for PSM
EE8	Battery, high capacity 100 Ah/760 CCA
EK1	Body builder connector under driver's seat
ES0	Jump start terminal
M46	Alternator 14 V/220 A

INTERIOR

CL1	Steering wheel w/ height and reach adjustment
D93	Deletion of partition
E46	12 V Power outlet in driver's seat base
EL8	Five speakers in cabin
EN0	Sound 5 with AM/FM, single-disc CD, MP3
F61	Rearview mirror
F66	Lockable glove compartment
FF5	Shelf above windshield
FJ1	Hinged lid for center console storage compartment
HH2	Electric heater booster
HH9	Air conditioning, front compartment
HZ9	Diesel heater booster - 5kW
J10	Speedometer, km/h
J65	Outside temperature display
L65	Interior lights, cargo/passenger compartment
S04	Adjustable passenger's seat
S22	Armrest for driver's seat
S25	Armrest for front passenger's seat
T74	Assist handle at sliding door on B-pillar
T85	Assist handle, left rear door
T86	Assist handle, right rear door
V43	Wood floor
V85	Smoker's package, front console
VH5	LIMA Cloth seats

EXTERIOR

D03	High roof
F68	Heated and power adjustable side mirrors
H21	Heat-insulating glass with windshield band
L05	Automatic daytime running lights
L94	Deletion of parking lamps
LB5	LED brake light
MZ0	BlueEFFICIENCY badge
P47	Front mud flaps
P48	Rear mud flaps
Q67	Tow hook, rear
R65	Spare wheel bracket below frame end
R87	Spare wheel
RF1	Tire brand, Continental
RH8	Tires - LT 245/75 R16
RM0	All-season tires
RM9	Tire brand, special request
RS3	Steel wheels 6.5J x 16
RW4	Deletion of tire sealant kit
T09	Sliding door with extended track
T12	Two stage opening for sliding door
T16	Sliding door, passenger side
W54	Rear doors, double wing, 270 degree opening

SAFETY/CONVENIENCE

BB3	Electronic Stability Program (ESP)
E07	Hill-start assist
F11	Keyless Entry
F13	Tire pressure monitoring
J58	Seat belt warning for driver's seat
RY2	Front and rear wireless tire pressure monitoring system
SA5	Front airbag, driver
SA6	Front airbag, passenger
Y43	Hydraulic jack

OTHER

IG3	Tracking Code
XC8	VIN visible from outside
XS7	Labels/publications printed in English/French
XY2	Model year 2012
Z44	NAFTA vehicle registration
Z65	Packing for sea transport
ZU7	National version for Canada
ZZ4	Mercedes-Benz specification

Sprinter 2500 Cargo 170" Ext.

MY12

Ordering Designation: 25C170E Baumuster: 906 637 13

Last updated: July 12, 2011

VEHICLE PRICING & OPTIONS

Prices are valid on date of delivery. Prices, design & equipment are subject to change without notice

	MSRP
Sprinter 2500 Cargo 170" Ext.	\$51,100

OPTIONAL PACKAGES

CODE	DESCRIPTION	MSRP
VPP	Convenience Package	\$500
CL4	Multifunction steering wheel w/ trip computer	
FZ9	Two additional master keys	
JK3	Instrument cluster with pixel-matrix display	
MS1	Cruise control	
VLP	Interior Lighting Package	\$300
	<i>replaces L65; not with VIP/D56/H08</i>	
L63	Ceiling lamp in cargo compartment	
LD0	Overhead control panel with 2 reading lamps	
VXP	Bi-xenon Headlamp Package	\$1,100
F46	Headlamp washing system	
L16	Halogen fog lamps	
LG1	Bi-xenon headlamps with cornering function	
VCP	Heated Seat Package	\$350
	<i>not with D64</i>	
H15	Heated front passenger's seat	
H16	Heated driver's seat	
VVP	Crew Van Package	\$2,200
	<i>not with S23/D05/VBP/VFP/VHP/VIP/VMP</i>	
H00	Warm/cool air duct to passenger compartment	
SD0	ISOFIX child seat attachment points	
U62	3-seater bench, first row, narrow	
V40	Crew cab floor assembly	
V46	Rubber floor mat in rear	
VA1	Interior trim, PVC, half height	
W16	Fixed window, front left in sidewall/sliding door	
W17	Fixed window, front right in sidewall/sliding door	
VBP	Basic Window Package	\$650
	<i>not with W78/VFP/VVP/VIP</i>	
H22	Rear window defroster	
VA7	Storage compartment with net, rear doors	
W17	Fixed window, front right in sidewall/sliding door	
W61	Fixed window, rear doors	
W70	Privacy glass	
VFP	Full Window Package	\$1,300
	<i>not with W78/VA3/VVP/VEP/VBP/VHP</i>	
H22	Rear window defroster	
VA7	Storage compartment with net, rear doors	
W02	Full window package	
W16	Fixed window, front left in sidewall/sliding door	
W17	Fixed window, front right in sidewall/sliding door	
W22	Fixed window, center left	
W23	Fixed window, center right	
W27	Fixed window, rear left	
W28	Fixed window, rear right	
W61	Fixed window, rear doors	

Sprinter 2500 Cargo 170" Ext.

MY12

Ordering Designation: 25C170E Baumuster: 906 637 13

Last updated: July 12, 2011

OPTIONAL PACKAGES (Continued)

CODE	DESCRIPTION	MSRP
VEP	Extended Cargo Package	\$700
	<i>not with D64/VVP/VFP/VIP/V46/ZE6</i>	
V42	Sidewall lashing rails on waist rail	
VC4	Cargo lashing rails, upper	
VV2	Load securing rail system	
YK3	Tensioning straps	
YK4	Lashing rail straps	
VMP	Mobility Prep. Package	\$790
	<i>replaces ED8; not with VVP</i>	
E28	Additional battery for retrofit	
E36	Cutoff relay for additional battery	
ED5	Programmable Special Module (PSM)	
ES2	12 V Power outlet in rear compartment	
H00	Warm/cool air duct to passenger compartment	
VGP	Comfort Seat Package	\$390
	<i>replaces S04; not with D64/VAP/VSP</i>	
SB1	Comfort driver's seat	
SB2	Comfort passenger's seat	
VSP	Swivel Seat Package	\$950
	<i>replaces S04; not with D64/S23/VAP/VGP</i>	
BE2	Folding handbrake lever	
S87	Driver's seat frame, low	
S88	Passenger's seat frame, low	
SB1	Comfort driver's seat	
SB2	Comfort passenger's seat	
SD2	Belt mounting point for deleted driver/passenger seat	
SR8	Swivel base for driver's seat	
SR9	Swivel base for passenger's seat	
VAP	Suspension Seat Package	\$820
	<i>replaces S04; not with D64/S23/VSP/VGP</i>	
S87	Driver's seat frame, low	
S88	Passenger's seat frame, low	
SB3	Suspension seat, comfort version, driver's seat	
SB4	Suspension seat, comfort version, passenger's seat	
VHP	Rear Heating Package (Cargo)	\$1,400
	<i>not with D64/V25/VIP/VFP/VVP</i>	
H01	Additional insulation for rear compartment	
H04	Additional insulation for front compartment	<i>note: if VHP is ordered on a vehicle with D50/D51/D53, V07 must be added from individual options</i>
H13	Additional heat exchanger	
VA3	Interior trim, washable, full height	
VIP	Luxury Interior Package	\$2,400
	<i>must have VFP; not with VA1/VA3/V25/VLP/VVP/VEP/VHP</i>	
H01	Additional insulation for rear compartment	
H04	Additional insulation for front compartment	
LD0	Overhead control panel with 2 reading lamps	
LD4	Convenience lighting in cargo/passenger compartment	
V21	Interior trim, luxury	
V31	Window pillar trim	
V36	Roof trim	
V64	Ashtrays, rear	

Sprinter 2500 Cargo 170" Ext.

MY12

Ordering Designation: 25C170E Baumuster: 906 637 13

Last updated: July 12, 2011

OPTIONAL EQUIPMENT

CODE	DESCRIPTION	MSRP
AR3	Axle ratio 4.182 <i>replaces AR2</i>	\$0
C39	Rear springs for 3.88-t weight variant, comfort <i>replaces C38</i>	\$150
CF2	Suspension w/Frt and Rr Stabilizer <i>replaces C40; not with CF4</i> <i>includes: C42 Rear axle stabilizer, under frame</i> <i>C45 Front axle stabilizer, reinforced</i>	\$380
CF4	Suspension w/ H.D. Frt and Rr Stabilizers <i>replaces C40+C47; not with CF2</i> <i>includes: C42 Rear axle stabilizer, under frame</i> <i>C45 Front axle stabilizer, reinforced</i>	\$460
CT1	Vibration damper	\$140
D05	Super-high roof <i>must have FF4 if ordered with a partition</i> note: <i>if vehicle is not arctic white, then code D06 must be ordered instead of D05</i>	\$2,500
D13	Mounting rails for roof rack	\$250
D22	Fixed rear sunroof <i>not with VIP/D56/H72/H08</i>	\$540
D50	Full partition <i>replaces D93+T74; not with D51/D53/D62/D64/VVP/VMP</i> <i>includes: T77 Assist handle at sliding door on partition</i>	\$270
D51	Full partition with 1 window <i>replaces D93+T74; not with D50/D53/D62/D64/VVP/VMP</i> <i>includes: T77 Assist handle at sliding door on partition</i>	\$310
D53	Full partition with 1 sliding window <i>replaces D93+T74; not with D50/D51/D62/D64/VVP/VMP</i> <i>includes: T77 Assist handle at sliding door on partition</i>	\$490
D62	Pre-installation for partition	\$140
D64	Full partition with sliding door <i>replaces D93+T74+S04+SA6</i> <i>includes: T77 Assist handle at sliding door on partition</i> <i>S20 Folding front passenger's seat</i> <i>S99 Deletion of passenger's seat base</i> note: <i>passenger airbag is deleted</i>	\$1,700
E28	Additional battery for retrofit <i>includes: E36 Cutoff relay for additional battery</i>	\$470
ED4	AGM Battery 95 Ah/850 CCA <i>replaces EE8</i>	\$190
ED5	Programmable Special Module (PSM) <i>replaces ED8</i>	\$300
EJ3	Audio 20 with AM/FM,6-disc CD, MP3, Bluetooth <i>replaces EN0; not with ERO</i>	\$900
ER0	Pre-installation for radio <i>replaces EN0; not with EJ3</i>	-\$300
ES2	12 V Power outlet in rear compartment	\$70
EZ8	PARKTRONIC	\$940
F49	Heated windshield <i>must have JA5+(VLP/VIP)</i>	\$330
FF4	Shelf above roof trim <i>must have D05</i>	\$290
FF8	Storage slot at front under roof liner - 1 DIN	\$100
FK3	Chrome grille	\$250
FR7	Rear view camera wiring prep <i>not with FR8</i>	\$80
FR8	Rear view camera <i>replaces FJ1; not with FR7</i>	\$900
FY1	Security alarm with interior motion sensor <i>must have VLP</i>	\$490
FZ9	Two additional master keys	\$140
H00	Warm/cool air duct to passenger compartment <i>not with D50/D51/D53/D64/S99</i>	\$80
H01	Additional insulation for rear compartment <i>must have V25/VA1/VA3</i>	\$140
H04	Additional insulation for front compartment <i>if ordered with D50/D51/D53 then must have V07</i>	\$140
H08	High-output A/C system in passenger compartment <i>must have ED4; not with VEP/VIP/VLP/VA3/D05/D22</i> <i>includes: V36 Roof trim</i>	\$2,900
H12	Heater, auxiliary front 5 kW <i>replaces HZ9; not with HZ5</i>	\$250
H13	Additional heat exchanger <i>not with D64/H88/T19/T93/VC5/VVP</i>	\$940
H16	Heated driver's seat <i>not with VCP</i>	\$210
H72	Electric roof fan <i>not with D22/H08/VIP</i>	\$480
H91	Deletion of Air-conditioning system <i>replaces HH9; not with H08</i>	-\$730
HZ5	Additional warm water heating with timer 10 kw <i>replaces HZ9; must have H13; not with H12/T19</i>	\$1,200
JA5	Automatic headlamps and windshield wipers <i>must have VLP/VIP</i>	\$410
JW0	Reverse warning system <i>not with FR8</i>	\$100

Sprinter 2500 Cargo 170" Ext.

MY12

Ordering Designation: 25C170E Baumuster: 906 637 13

Last updated: July 12, 2011

OPTIONAL EQUIPMENT (Continued)

CODE	DESCRIPTION	MSRP
L16	Halogen fog lamps	\$210
LB9	Illuminated exits	\$130
M53	High idle preset <i>includes: ED5 Programmable Special Module (PSM)</i>	not with MT4 \$650
MD3	Speed limiter - 120 km/h	\$70
MS1	Cruise control	\$390
MT4	High idle - driver adjustable <i>includes: ED5 Programmable Special Module (PSM)</i>	not with M53 \$680
N62	Pulley for additional alternator	not with N63/H08 \$440
N63	Pulley for additional compressor	not with N62/H08 \$440
Q24	Cross member with 5,000lbs towing capacity	\$250
R91	Deletion of spare wheel	replaces R87; must have R92+RR7 -\$160
R92	Deletion of spare wheel bracket	replaces R65; must have R91 \$0
RH0	Tire brand, Kumho	replaces RF1; not with RM1 \$0
RL5	Light-alloy wheels 6.5 J x 16	replaces RS3 \$920
RM1	Winter tires	replaces RM0 \$140
RR7	Tire sealant kit with electric compressor	replaces RW4 \$30
S23	Twin front passenger seats <i>includes: S78 Assist handle for inner seat</i>	replaces S04+S25; not with D64/SB2/VAP/VSP/VGP \$520
SB1	Comfort driver's seat	not with VAP/VSP/VGP \$220
SH6	Thorax airbag, driver	not with SH7 \$340
SH7	Thorax airbag, driver/passenger	not with D64/S23/SH6 \$480
SH9	Window airbag, driver/passenger	\$820
T19	Sliding door, driver's side	not with VHP/VIP \$890
T93	Deletion of sliding door	replaces T09+T16; not with T19/VVP \$0
V07	Rear wall lining on back of partition	must have (D50/D51/D53)+H04 \$340
V25	Interior trim, hardboard, half height	not with VA1/VA3/V21/VHP/VIP/VVP \$190
V46	Rubber floor mat in rear	\$340
V93	Deletion of wood floor	replaces V43 -\$360
VA1	Interior trim, PVC, half height	\$410
VA3	Interior trim, washable, full height	not with V25/VIP/VFP/VVP/VHP \$460
VC5	Aluminum entrance panel, sliding door	not with H13/T19/T93/VVP/VEP/VHP \$70
VU9	Leatherette, black	replaces VH5; not with D64 \$80
W16	Fixed window, front left in sidewall/sliding door	\$180
W17	Fixed window, front right in sidewall/sliding door	\$180
W61	Fixed window, rear doors <i>includes: H22 Rear window defroster VA7 Storage compartment with net, rear doors</i>	not with VFP/VBP/W78 \$450
W70	Privacy glass	must have Wxx/VVP/VFP \$640
W73	Step for rear wall door	not with Q24 \$180
W78	Fixed window with washer/wipers, rear doors <i>includes: H22 Rear window defroster VA7 Storage compartment with net, rear doors</i>	not with VFP/VBP/W61 \$640
-	Special Paint	\$600
-	Metallic Paint	\$1,100

FACTORY STANDARD EQUIPMENT**POWERTRAIN/SUSPENSION**

AR3	Axle ratio 4.182
C40	Front axle stabilizer
G40	5-speed automatic transmission (W5A 380)
K60	Straight rear-exiting exhaust
KB0	100-litre fuel tank
KL1	Auxiliary heater fuel sending unit
KL5	Fuel filter with water separator
KP0	Bodywork SCR
MG5	3.0L V6 BlueTEC Diesel (OM 642 -188hp/325lb-ft)
MH1	EPA10 Compliant low-emission engine
XG9	GVWR 4,490 kg (9,899 lbs)

ELECTRONIC SYSTEMS

E30	Battery quick-disconnect
E40	Trailer hitch prep package, 7-pole
ED8	Electrical pre-installation for PSM
EE8	Battery, high capacity 100 Ah/760 CCA
EK1	Body builder connector under driver's seat
ES0	Jump start terminal
M46	Alternator 14 V/220 A

INTERIOR

CL1	Steering wheel w/ height and reach adjustment
D93	Deletion of partition
E46	12 V Power outlet in driver's seat base
EL8	Five speakers in cabin
EN0	Sound 5 with AM/FM, single-disc CD, MP3
F61	Rearview mirror
F66	Lockable glove compartment
FF5	Shelf above windshield
FJ1	Hinged lid for center console storage compartment
HH2	Electric heater booster
HH9	Air conditioning, front compartment
HZ9	Diesel heater booster - 5kW
J10	Speedometer, km/h
J65	Outside temperature display
L65	Interior lights, cargo/passenger compartment
S04	Adjustable passenger's seat
S22	Armrest for driver's seat
S25	Armrest for front passenger's seat
T74	Assist handle at sliding door on B-pillar
T85	Assist handle, left rear door
T86	Assist handle, right rear door
V43	Wood floor
V85	Smoker's package, front console
VH5	LIMA Cloth seats

EXTERIOR

D03	High roof
F68	Heated and power adjustable side mirrors
H21	Heat-insulating glass with windshield band
L05	Automatic daytime running lights
L94	Deletion of parking lamps
LB5	LED brake light
MZ0	BlueEFFICIENCY badge
P47	Front mud flaps
P48	Rear mud flaps
R65	Spare wheel bracket below frame end
R87	Spare wheel
RD9	Tire brand, unspecified
RH7	Tires - LT 215/85 R16
RM0	All-season tires
RS6	Steel wheels 5.5J x 16
RW4	Deletion of tire sealant kit
T09	Sliding door with extended track
T12	Two stage opening for sliding door
T16	Sliding door, passenger side
W54	Rear doors, double wing, 270 degree opening

SAFETY/CONVENIENCE

BB3	Electronic Stability Program (ESP)
E07	Hill-start assist
FI1	Keyless Entry
J58	Seat belt warning for driver's seat
SA5	Front airbag, driver
SA6	Front airbag, passenger
Y43	Hydraulic jack

OTHER

IG3	Tracking Code
XC8	VIN visible from outside
XS7	Labels/publications printed in English/French
XY2	Model year 2012
Z44	NAFTA vehicle registration
Z65	Packing for sea transport
ZU7	National version for Canada
ZZ4	Mercedes-Benz specification

Sprinter 3500 Cargo 144"

MY12

Ordering Designation: 35C144 Baumuster: 906 653 13

Last updated: July 12, 2011

VEHICLE PRICING & OPTIONS

Prices are valid on date of delivery. Prices, design & equipment are subject to change without notice

MSRP

Sprinter 3500 Cargo 144"

\$49,300

OPTIONAL PACKAGES

CODE	DESCRIPTION	MSRP
VPP	Convenience Package	\$500
CL4	Multifunction steering wheel w/ trip computer	
FZ9	Two additional master keys	
JK3	Instrument cluster with pixel-matrix display	
MS1	Cruise control	
VLP	Interior Lighting Package	\$300
	<i>replaces L65; not with VIP</i>	
L63	Ceiling lamp in cargo compartment	
LD0	Overhead control panel with 2 reading lamps	
VXP	Bi-xenon Headlamp Package	\$1,100
F46	Headlamp washing system	
L16	Halogen fog lamps	
LG1	Bi-xenon headlamps with cornering function	
VCP	Heated Seat Package	\$350
	<i>not with D64</i>	
H15	Heated front passenger's seat	
H16	Heated driver's seat	
VEP	Extended Cargo Package	\$700
	<i>not with D64/VFP/VIP/V46</i>	
V42	Sidewall lashing rails on waist rail	
VC4	Cargo lashing rails, upper	
VV2	Load securing rail system	
YK3	Tensioning straps	
YK4	Lashing rail straps	
VBP	Basic Window Package	\$650
	<i>not with W78/VFP/VIP</i>	
H22	Rear window defroster	
VA7	Storage compartment with net, rear doors	
W17	Fixed window, front right in sidewall/sliding door	
W61	Fixed window, rear doors	
W70	Privacy glass	
VFP	Full Window Package	\$1,000
	<i>not with W78/VA3/VEP/VBP/VHP</i>	
H22	Rear window defroster	
VA7	Storage compartment with net, rear doors	
W02	Full window package	
W16	Fixed window, front left in sidewall/sliding door	
W17	Fixed window, front right in sidewall/sliding door	
W27	Fixed window, rear left	
W28	Fixed window, rear right	
W61	Fixed window, rear doors	
VGP	Comfort Seat Package	\$390
	<i>not with VSP/VAP</i>	
SB1	Comfort driver's seat	
SB2	Comfort passenger's seat	

Sprinter 3500 Cargo 144"

MY12

Ordering Designation: 35C144 Baumuster: 906 653 13

Last updated: July 12, 2011

OPTIONAL PACKAGES (Continued)

CODE	DESCRIPTION	MSRP
VMP	Mobility Prep. Package	\$790
	<i>replaces ED8+L65; not with VHP</i>	
E28	Additional battery for retrofit	
E36	Cutoff relay for additional battery	
ED5	Programmable Special Module (PSM)	
ES2	12 V Power outlet in rear compartment	
H00	Warm/cool air duct to passenger compartment	
VVP	Crew Van Package	\$2,200
	<i>not with S23/D05/VBP/VFP/VHP/VIP/VMP</i>	
H00	Warm/cool air duct to passenger compartment	
SD0	ISOFIX child seat attachment points	
U62	3-seater bench, first row, narrow	
V40	Crew cab floor assembly	
V46	Rubber floor mat in rear	
V25	Interior trim, hardboard, half height	
W16	Fixed window, front left in sidewall/sliding door	
W17	Fixed window, front right in sidewall/sliding door	
VSP	Swivel Seat Package	\$950
	<i>replaces S04; not with D64/S23/VAP/VGP</i>	
BE2	Folding handbrake lever	
S87	Driver's seat frame, low	
S88	Passenger's seat frame, low	
SB1	Comfort driver's seat	
SB2	Comfort passenger's seat	
SD2	Belt mounting point for deleted driver/passenger seat	
SR8	Swivel base for driver's seat	
SR9	Swivel base for passenger's seat	
VAP	Suspension Seat Package	\$820
	<i>replaces S04; not with D64/S23/VSP/VGP</i>	
S87	Driver's seat frame, low	
S88	Passenger's seat frame, low	
SB3	Suspension seat, comfort version, driver's seat	
SB4	Suspension seat, comfort version, passenger's seat	
VHP	Rear Heating Package (Cargo)	\$1,400
	<i>not with D64/V25/VIP/VFP</i>	
H01	Additional insulation for rear compartment	
H04	Additional insulation for front compartment	
H13	Additional heat exchanger	
VA3	Interior trim, washable, full height	
	note: if VHP is ordered on a vehicle with D50/D51/D53, V07 must be added from individual options	
VIP	Luxury Interior Package	\$2,400
	<i>must have VFP; not with VA1/VA3/V25/VLP/VEP/VHP/</i>	
H01	Additional insulation for rear compartment	
H04	Additional insulation for front compartment	
LD0	Overhead control panel with 2 reading lamps	
LD4	Convenience lighting in cargo/passenger compartment	
V21	Interior trim, luxury	
V31	Window pillar trim	
V36	Roof trim	
V64	Ashtrays, rear	

Sprinter 3500 Cargo 144"

MY12

Ordering Designation: 35C144 Baumuster: 906 653 13

Last updated: July 12, 2011

OPTIONAL EQUIPMENT

CODE	DESCRIPTION	MSRP
A50	Front axle, reinforced <i>must have CF6</i>	\$330
AR2	Axle ratio 3.923 <i>replaces AR3</i>	\$0
CF2	Suspension w/ Frt and Rr Stabilizer <i>replaces C40; not with CF3/CF4</i> <i>includes: C42 Rear axle stabilizer, under frame</i> <i>C45 Front axle stabilizer, reinforced</i>	\$380
CF3	Suspension w/ H.D. Rr Stabilizer <i>replaces C40; not with CF2/CF4</i> <i>includes: C43 Rear axle stabilizer, reinforced, under frame</i> <i>C45 Front axle stabilizer, reinforced</i>	\$360
CF4	Suspension w/ H.D. Frt and Rr Stabilizers <i>replaces C40; not with CF2/CF3/CF6</i> <i>includes: C42 Rear axle stabilizer, under frame</i> <i>C45 Front axle stabilizer, reinforced</i> <i>CF6 Front springs and dampers, reinforced</i>	\$530
CF6	Front springs and dampers, reinforced <i>must have A50; not with CF2/CF3</i>	\$0
D13	Mounting rails for roof rack	\$250
D22	Fixed rear sunroof <i>not with VIP/H72</i>	\$400
D50	Full partition <i>replaces D93+T74; not with D51/D53/D62/D64/VMP</i> <i>includes: T77 Assist handle at sliding door on partition</i>	\$270
D51	Full partition with 1 window <i>replaces D93+T74; not with D50/D53/D62/D64/VMP</i> <i>includes: T77 Assist handle at sliding door on partition</i>	\$310
D53	Full partition with 1 sliding window <i>replaces D93+T74; not with D50/D51/D62/D64/VMP</i> <i>includes: T77 Assist handle at sliding door on partition</i>	\$490
D62	Pre-installation for partition	\$140
D64	Full partition with sliding door <i>replaces D93+T74+S04+SA6</i> <i>not with D50/D51/D53/D62/T19/T93/VHP/VIP/VMP</i> <i>includes: T77 Assist handle at sliding door on partition</i> <i>S20 Folding front passenger's seat</i> <i>S99 Deletion of passenger's seat base</i> note: passenger airbag is deleted	\$1,700
E28	Additional battery for retrofit <i>includes: E36 Cutoff relay for additional battery</i>	\$470
ED4	AGM Battery 95 Ah/850 CCA <i>replaces EE8</i>	\$190
ED5	Programmable Special Module (PSM) <i>replaces ED8</i>	\$300
EJ3	Audio 20 with AM/FM,6-disc CD, MP3, Bluetooth <i>replaces EN0; not with ERO</i>	\$900
ER0	Pre-installation for radio <i>replaces EN0; not with EJ3</i>	-\$300
ES2	12 V Power outlet in rear compartment	\$70
EZ8	PARKTRONIC	\$940
F49	Heated windshield <i>must have JA5+(VLP/VIP)</i>	\$330
FF8	Storage slot at front under roof liner - 1 DIN	\$100
FK3	Chrome grille	\$250
FR7	Rear view camera wiring prep <i>not with FR8</i>	\$80
FR8	Rear view camera <i>replaces FJ1; not with FR7</i>	\$900
FY1	Security alarm with interior motion sensor <i>must have VLP</i>	\$490
FZ9	Two additional master keys	\$140
H00	Warm/cool air duct to passenger compartment <i>not with D50/D51/D53/D64/S99</i>	\$80
H01	Additional insulation for rear compartment <i>must have V25/VA1/VA3</i>	\$140
H04	Additional insulation for front compartment <i>if ordered with D50/D51/D53 then must have V07</i>	\$140
H08	High-output A/C system in passenger compartment <i>must have ED4; not with VEP/VIP/VLP/VA3/D05/D22</i> <i>includes: V36 Roof trim</i>	\$2,900
H12	Heater, auxiliary front 5 kW <i>replaces HZ9; not with HZ5</i>	\$250
H13	Additional heat exchanger <i>not with D64/H88/T19/T93/VC5/VVP</i>	\$940
H16	Heated driver's seat	\$210
H72	Electric roof fan <i>not with D22/H08/VIP</i>	\$480
H91	Deletion of Air-conditioning system <i>replaces HH9; not with H08</i>	-\$730
HZ5	Additional warm water heating with timer 10 kw <i>replaces HZ9; must have H13; not with H12/T19</i>	\$1,200

Sprinter 3500 Cargo 144"

MY12

Ordering Designation: 35C144 Baumuster: 906 653 13

Last updated: July 12, 2011

OPTIONAL EQUIPMENT (Continued)

CODE	DESCRIPTION	MSRP
JA5	Automatic headlamps and windshield wipers <i>must have VLP/VIP</i>	\$410
JW0	Reverse warning system <i>not with FR8</i>	\$100
L16	Halogen fog lamps	\$210
LB9	Illuminated exits	\$130
M53	High idle preset <i>includes: ED5 Programmable Special Module (PSM)</i> <i>not with MT4</i>	\$650
MD3	Speed limiter - 120 km/h	\$70
MS1	Cruise control	\$390
MT4	High idle - driver adjustable <i>includes: ED5 Programmable Special Module (PSM)</i> <i>not with M53</i>	\$680
N62	Pulley for additional alternator <i>not with N63</i>	\$440
N63	Pulley for additional compressor <i>not with N62</i>	\$440
QA2	Cross member with 7,500lbs towing capacity	\$250
R91	Deletion of spare wheel <i>replaces R87; must have R92+RR7</i>	-\$160
R92	Deletion of spare wheel bracket <i>replaces R65; must have R91</i>	\$0
RH0	Tire brand, Kumho <i>replaces RF1</i>	\$0
RM1	Winter tires <i>replaces RMO</i>	\$140
RR7	Tire sealant kit with electric compressor <i>replaces RW4</i>	\$30
S23	Twin front passenger seats <i>includes: S78 Assist handle for inner seat</i> <i>replaces S04+S25; not with D64/SB2/VAP/VSP/VGP</i>	\$520
SB1	Comfort driver's seat <i>not with VAP/VGP/VSP</i>	\$220
SH6	Thorax airbag, driver <i>not with SH7</i>	\$340
SH7	Thorax airbag, driver/passenger <i>not with D64/S23/SH6</i>	\$480
SH9	Window airbag, driver/passenger	\$820
T19	Sliding door, driver's side <i>not with VHP/VIP</i>	\$890
T93	Deletion of sliding door <i>replaces T09+T16; not with T19</i>	\$0
V07	Rear wall lining on back of partition <i>must have (D50/D51/D53)+H04</i>	\$340
V25	Interior trim, hardboard, half height <i>not with VA1/VA3/V21/VHP/VIP</i>	\$190
V46	Rubber floor mat in rear	\$340
V93	Deletion of wood floor <i>replaces V43</i>	-\$360
VA1	Interior trim, PVC, half height	\$410
VA3	Interior trim, washable, full height <i>not with V25/VIP/VFP/VHP</i>	\$460
VC5	Aluminum entrance panel, sliding door <i>not with H13/T19/T93/VEP/VHP</i>	\$70
VU9	Leatherette, black <i>replaces VH5; not with D64</i>	\$80
W16	Fixed window, front left in sidewall/sliding door	\$180
W17	Fixed window, front right in sidewall/sliding door	\$180
W61	Fixed window, rear doors <i>includes: H22 Rear window defroster</i> <i>VA7 Storage compartment with net, rear doors</i>	\$450
W70	Privacy glass <i>must have Wxx/VFP/VVP</i>	\$480
W73	Step for rear wall door <i>not with QA2</i>	\$180
W78	Fixed window with washer/wipers, rear doors <i>includes: H22 Rear window defroster</i> <i>VA7 Storage compartment with net, rear doors</i>	\$640
Y26	Wheel chocks	\$35
Z2D	GVWR 5,000 kg (11,030 lbs) <i>replaces XG9</i>	\$680
-	Special Paint	\$600
-	Metallic Paint	\$1,100

FACTORY STANDARD EQUIPMENT

POWERTRAIN/SUSPENSION

- AR3 Axle ratio 4.182
- C40 Front axle stabilizer
- G40 5-speed automatic transmission (W5A 380)
- K60 Straight rear-exiting exhaust
- KB0 100-litre fuel tank
- KL1 Auxiliary heater fuel sending unit
- KL5 Fuel filter with water separator
- KP0 Bodywork SCR
- MG5 3.0L V6 BlueTEC Diesel (OM 642 -188hp/325lb-ft)
- MH1 EPA10 Compliant low-emission engine
- XG9 GVWR 4,490 kg (9,899 lbs)

ELECTRONIC SYSTEMS

- E30 Battery quick-disconnect
- E40 Trailer hitch prep package, 7-pole
- ED8 Electrical pre-installation for PSM
- EE8 Battery, high capacity 100 Ah/760 CCA
- EK1 Body builder connector under driver's seat
- ES0 Jump start terminal
- M46 Alternator 14 V/220 A

INTERIOR

- CL1 Steering wheel w/ height and reach adjustment
- D93 Deletion of partition
- E46 12 V Power outlet in driver's seat base
- EL8 Five speakers in cabin
- EN0 Sound 5 with AM/FM, single-disc CD, MP3
- F61 Rearview mirror
- F66 Lockable glove compartment
- FF5 Shelf above windshield
- FJ1 Hinged lid for center console storage compartment
- HH2 Electric heater booster
- HH9 Air conditioning, front compartment
- HZ9 Diesel heater booster - 5kW
- J10 Speedometer, km/h
- J65 Outside temperature display
- L65 Interior lights, cargo/passenger compartment
- S04 Adjustable passenger's seat
- S22 Armrest for driver's seat
- S25 Armrest for front passenger's seat
- T74 Assist handle at sliding door on B-pillar
- T85 Assist handle, left rear door
- T86 Assist handle, right rear door
- V43 Wood floor
- V85 Smoker's package, front console
- VH5 LIMA Cloth seats

EXTERIOR

- D03 High roof
- F68 Heated and power adjustable side mirrors
- H21 Heat-insulating glass with windshield band
- L05 Automatic daytime running lights
- L94 Deletion of parking lamps
- LB5 LED brake light
- MZ0 BlueEFFICIENCY badge
- P47 Front mud flaps
- P48 Rear mud flaps
- R65 Spare wheel bracket below frame end
- R87 Spare wheel
- RD9 Tire brand, unspecified
- RH7 Tires - LT 215/85 R16
- RM0 All-season tires
- RS6 Steel wheels 5.5J x 16
- RW4 Deletion of tire sealant kit
- T09 Sliding door with extended track
- T12 Two stage opening for sliding door
- T16 Sliding door, passenger side
- W54 Rear doors, double wing, 270 degree opening

SAFETY/CONVENIENCE

- BB3 Electronic Stability Program (ESP)
- E07 Hill-start assist
- F11 Keyless Entry
- J58 Seat belt warning for driver's seat
- SA5 Front airbag, driver
- SA6 Front airbag, passenger
- Y43 Hydraulic jack

OTHER

- IG3 Tracking Code
- XC8 VIN visible from outside
- XS7 Labels/publications printed in English/French
- XY2 Model year 2012
- Z44 NAFTA vehicle registration
- Z65 Packing for sea transport
- ZU7 National version for Canada
- ZZ4 Mercedes-Benz specification

Sprinter 3500 Cargo 170"

MY12

Ordering Designation: 35C170 Baumuster: 906 655 13

Last updated: July 12, 2011

VEHICLE PRICING & OPTIONS

Prices are valid on date of delivery. Prices, design & equipment are subject to change without notice

MSRP

Sprinter 3500 Cargo 170"

\$52,000

OPTIONAL PACKAGES

CODE	DESCRIPTION	MSRP
VPP	Convenience Package	\$500
CL4	Multifunction steering wheel w/ trip computer	
FZ9	Two additional master keys	
JK3	Instrument cluster with pixel-matrix display	
MS1	Cruise control	
VLP	Interior Lighting Package	\$300
	<i>replaces L65; not with VIP</i>	
L63	Ceiling lamp in cargo compartment	
LD0	Overhead control panel with 2 reading lamps	
VXP	Bi-xenon Headlamp Package	\$1,100
F46	Headlamp washing system	
L16	Halogen fog lamps	
LG1	Bi-xenon headlamps with cornering function	
VCP	Heated Seat Package	\$350
	<i>not with D64</i>	
H15	Heated front passenger's seat	
H16	Heated driver's seat	
VEP	Extended Cargo Package	\$700
	<i>not with D64/VFP/VIP/V46</i>	
V42	Sidewall lashing rails on waist rail	
VC4	Cargo lashing rails, upper	
VV2	Load securing rail system	
YK3	Tensioning straps	
YK4	Lashing rail straps	
VGP	Comfort Seat Package	\$390
	<i>not with VAP/VSP</i>	
SB1	Comfort driver's seat	
SB2	Comfort passenger's seat	
VBP	Basic Window Package	\$650
	<i>not with W78/VFP/VIP</i>	
H22	Rear window defroster	
VA7	Storage compartment with net, rear doors	
W17	Fixed window, front right in sidewall/sliding door	
W61	Fixed window, rear doors	
W70	Privacy glass	
VFP	Full Window Package	\$1,300
	<i>not with W78/VA3/VEP/VBP/VHP</i>	
H22	Rear window defroster	
VA7	Storage compartment with net, rear doors	
W02	Full window package	
W16	Fixed window, front left in sidewall/sliding door	
W17	Fixed window, front right in sidewall/sliding door	
W22	Fixed window, center left	
W23	Fixed window, center right	
W27	Fixed window, rear left	
W28	Fixed window, rear right	
W61	Fixed window, rear doors	

OPTIONAL PACKAGES (Continued)

CODE	DESCRIPTION	MSRP
VMP	Mobility Prep. Package	\$790
	<i>replaces ED8+L65</i>	
E28	Additional battery for retrofit	
E36	Cutoff relay for additional battery	
ED5	Programmable Special Module (PSM)	
ES2	12 V Power outlet in rear compartment	
H00	Warm/cool air duct to passenger compartment	
VVP	Crew Van Package	\$2,200
	<i>not with S23/D05/VBP/VFP/VHP/VIP/VMP</i>	
H00	Warm/cool air duct to passenger compartment	
SD0	ISOFIX child seat attachment points	
U62	3-seater bench, first row, narrow	
V40	Crew cab floor assembly	
V46	Rubber floor mat in rear	
V25	Interior trim, hardboard, half height	
W16	Fixed window, front left in sidewall/sliding door	
W17	Fixed window, front right in sidewall/sliding door	
VSP	Swivel Seat Package	\$950
	<i>replaces S04; not with D64/S23/VAP/VGP</i>	
BE2	Folding handbrake lever	
S87	Driver's seat frame, low	
S88	Passenger's seat frame, low	
SB1	Comfort driver's seat	
SB2	Comfort passenger's seat	
SD2	Belt mounting point for deleted driver/passenger seat	
SR8	Swivel base for driver's seat	
SR9	Swivel base for passenger's seat	
VAP	Suspension Seat Package	\$820
	<i>replaces S04; not with D64/S23/VSP/VPP</i>	
S87	Driver's seat frame, low	
S88	Passenger's seat frame, low	
SB3	Suspension seat, comfort version, driver's seat	
SB4	Suspension seat, comfort version, passenger's seat	
VHP	Rear Heating Package	\$1,400
	<i>not with D64/V25/VIP/VFP</i>	
H01	Additional insulation for rear compartment	
H04	Additional insulation for front compartment	
H13	Additional heat exchanger	
VA3	Interior trim, washable, full height	
	note: if VHP is ordered on a vehicle with D50/D51/D53, V07 must be added from individual options	
VIP	Luxury Interior Package	\$2,400
	<i>must have VFP; not with VA1/VA3/V25/VLP/VEP/VHP</i>	
H01	Additional insulation for rear compartment	
H04	Additional insulation for front compartment	
LD0	Overhead control panel with 2 reading lamps	
LD4	Convenience lighting in cargo/passenger compartment	
V21	Interior trim, luxury	
V31	Window pillar trim	
V36	Roof trim	
V64	Ashtrays, rear	

Sprinter 3500 Cargo 170"

MY12

Ordering Designation: 35C170 Baumuster: 906 655 13

Last updated: July 12, 2011

OPTIONAL EQUIPMENT

CODE	DESCRIPTION	MSRP
A50	Front axle, reinforced <i>must have CF6</i>	\$330
AR2	Axle ratio 3.923 <i>replaces AR3</i>	\$0
CF2	Suspension w/Frt and Rr Stabilizer <i>replaces C40; not with CF3/CF4</i> <i>includes: C42 Rear axle stabilizer, under frame</i> <i>C45 Front axle stabilizer, reinforced</i>	\$380
CF3	Suspension w/ H.D. Rr Stabilizer <i>replaces C40; not with CF2/CF4</i> <i>includes: C43 Rear axle stabilizer, reinforced, under frame</i> <i>C45 Front axle stabilizer, reinforced</i>	\$360
CF4	Suspension w/ H.D. Frt and Rr Stabilizers <i>replaces C40; not with CF2/CF3/CF6</i> <i>includes: C42 Rear axle stabilizer, under frame</i> <i>C45 Front axle stabilizer, reinforced</i> <i>CF6 Front springs and dampers, reinforced</i>	\$530
CF6	Front springs and dampers, reinforced <i>must have A50; not with CF2/CF3</i>	\$0
D05	Super-high roof <i>must have FF4 if ordered with a partition</i> note: <i>if vehicle is not arctic white, then code D06 must be ordered instead of D05</i>	\$2,500
D13	Mounting rails for roof rack	\$250
D22	Fixed rear sunroof <i>not with VIP/H72</i>	\$540
D50	Full partition <i>replaces D93+T74; not with D51/D53/D62/D64/VMP</i> <i>includes: T77 Assist handle at sliding door on partition</i>	\$270
D51	Full partition with 1 window <i>replaces D93+T74; not with D50/D53/D62/D64/VMP</i> <i>includes: T77 Assist handle at sliding door on partition</i>	\$310
D53	Full partition with 1 sliding window <i>replaces D93+T74; not with D50/D51/D62/D64/VMP</i> <i>includes: T77 Assist handle at sliding door on partition</i>	\$490
D62	Pre-installation for partition	\$140
D64	Full partition with sliding door <i>replaces D93+T74+S04+SA6</i> <i>includes: T77 Assist handle at sliding door on partition</i> <i>S20 Folding front passenger's seat</i> <i>S99 Deletion of passenger's seat base</i> note: <i>passenger airbag is deleted</i> <i>not with D50/D51/D53/D62/T19/T93/VHP/VIP/VMP</i>	\$1,700
E28	Additional battery for retrofit <i>includes: E36 Cutoff relay for additional battery</i>	\$470
ED4	AGM Battery 95 Ah/850 CCA <i>replaces EE8</i>	\$190
ED5	Programmable Special Module (PSM) <i>replaces ED8</i>	\$300
EJ3	Audio 20 with AM/FM,6-disc CD, MP3, Bluetooth <i>replaces EN0; not with ER0</i>	\$900
ER0	Pre-installation for radio <i>replaces EN0; not with EJ3</i>	-\$300
ES2	12 V Power outlet in rear compartment	\$70
EZ8	PARKTRONIC	\$940
F49	Heated windshield <i>must have JA5+(VLP/VIP)</i>	\$330
FF4	Shelf above roof trim <i>must have D05</i>	\$290
FF8	Storage slot at front under roof liner - 1 DIN	\$100
FK3	Chrome grille	\$250
FR7	Rear view camera wiring prep <i>not with FR8</i>	\$80
FR8	Rear view camera <i>replaces FJ1; not with FR7</i>	\$900
FY1	Security alarm with interior motion sensor <i>must have VLP</i>	\$490
FZ9	Two additional master keys	\$140
H00	Warm/cool air duct to passenger compartment <i>not with D50/D51/D53/D64/S99</i>	\$80
H01	Additional insulation for rear compartment <i>must have V25/VA1/VA3</i>	\$140
H04	Additional insulation for front compartment <i>if ordered with D50/D51/D53 then must have V07</i>	\$140
H08	High-output A/C system in passenger compartment <i>must have ED4; not with VEP/VIP/VLP/VA3/D05/D22</i> <i>includes: V36 Roof trim</i>	\$2,900
H12	Heater, auxiliary front 5 kW <i>replaces HZ9; not with HZ5</i>	\$250
H13	Additional heat exchanger <i>not with D64/H88/T19/T93/VC5/VVP</i>	\$940
H16	Heated driver's seat	\$210
H72	Electric roof fan <i>not with D22/H08/VIP</i>	\$480
H91	Deletion of Air-conditioning system <i>replaces HH9; not with H08</i>	-\$730
HZ5	Additional warm water heating with timer 10 kw <i>replaces HZ9; must have H13; not with H12/T19</i>	\$1,200

Sprinter 3500 Cargo 170"

MY12

Ordering Designation: 35C170 Baumuster: 906 655 13

Last updated: July 12, 2011

OPTIONAL EQUIPMENT (Continued)

CODE	DESCRIPTION	MSRP
JA5	Automatic headlamps and windshield wipers <i>must have VLP/VIP</i>	\$410
JW0	Reverse warning system <i>not with FR8</i>	\$100
L16	Halogen fog lamps	\$210
LB9	Illuminated exits	\$130
M53	High idle preset <i>includes: ED5 Programmable #N/A</i> <i>not with MT4</i>	\$650
MD3	Speed limiter - 120 km/h	\$70
MS1	Cruise control	\$390
MT4	High idle - driver adjustable <i>includes: ED5 Programmable #N/A</i> <i>not with M53</i>	\$680
N62	Pulley for additional alternator <i>not with N63</i>	\$440
N63	Pulley for additional compressor <i>not with N62</i>	\$440
QA2	Cross member with 7,500lbs towing capacity	\$250
R91	Deletion of spare wheel <i>replaces R87; must have R92+RR7</i>	-\$160
R92	Deletion of spare wheel bracket <i>replaces R65; must have R91</i>	\$0
RH0	Tire brand, Kumho	\$0
RM1	Winter tires <i>replaces RM0</i>	\$140
RR7	Tire sealant kit with electric compressor <i>replaces RW4</i>	\$30
S23	Twin front passenger seats <i>includes: S78 Assist handle for inner seat</i> <i>replaces S04+S25; not with D64/SB2/VAP/VSP/VGP</i>	\$520
SB1	Comfort driver's seat <i>not with VAP/VSP/VGP</i>	\$220
SH6	Thorax airbag, driver <i>not with SH7</i>	\$340
SH7	Thorax airbag, driver/passenger <i>not with D64/S23/SH6</i>	\$480
SH9	Window airbag, driver/passenger	\$820
T19	Sliding door, driver's side <i>not with VHP/VIP</i>	\$890
T93	Deletion of sliding door <i>replaces T09+T16; not with T19</i>	\$0
V07	Rear wall lining on back of partition <i>must have (D50/D51/D53)+H04</i>	\$340
V25	Interior trim, hardboard, half height <i>not with VA1/VA3/V21/VHP/VIP</i>	\$190
V46	Rubber floor mat in rear	\$340
V93	Deletion of wood floor <i>replaces V43</i>	-\$360
VA1	Interior trim, PVC, half height	\$410
VA3	Interior trim, washable, full height <i>not with V25/VIP/VFP/VHP</i>	\$460
VC5	Aluminum entrance panel, sliding door <i>not with H13/T19/T93/VEP/VHP</i>	\$70
VU9	Leatherette, black <i>replaces VH5; not with D64</i>	\$80
W16	Fixed window, front left in sidewall/sliding door	\$180
W17	Fixed window, front right in sidewall/sliding door	\$180
W61	Fixed window, rear doors <i>includes: H22 Rear window defroster</i> <i>VA7 Storage compartment with net, rear doors</i>	\$450
W70	Privacy glass <i>must have Wxx/VFP/VVP</i>	\$640
W73	Step for rear wall door <i>not with QA2</i>	\$180
W78	Fixed window with washer/wipers, rear doors <i>includes: H22 Rear window defroster</i> <i>VA7 Storage compartment with net, rear doors</i>	\$640
Y26	Wheel chocks	\$35
Z2D	GVWR 5,000 kg (11,030 lbs) <i>replaces XG9</i>	\$680
-	Special Paint	\$600
-	Metallic Paint	\$1,100

FACTORY STANDARD EQUIPMENT**POWERTRAIN/SUSPENSION**

AR3	Axle ratio 4.182
C40	Front axle stabilizer
G40	5-speed automatic transmission (W5A 380)
K60	Straight rear-exiting exhaust
KB0	100-litre fuel tank
KL1	Auxiliary heater fuel sending unit
KL5	Fuel filter with water separator
KP0	Bodywork SCR
MG5	3.0L V6 BlueTEC Diesel (OM 642 - 188hp/325lb-ft)
MH1	EPA10 Compliant low-emission engine
XG9	GVWR 4,490 kg (9,899 lbs)

ELECTRONIC SYSTEMS

E30	Battery quick-disconnect
E40	Trailer hitch prep package, 7-pole
ED8	Electrical pre-installation for PSM
EE8	Battery, high capacity 100 Ah/760 CCA
EK1	Body builder connector under driver's seat
ES0	Jump start terminal
M46	Alternator 14 V/220 A

INTERIOR

CL1	Steering wheel w/ height and reach adjustment
D93	Deletion of partition
E46	12 V Power outlet in driver's seat base
EL8	Five speakers in cabin
EN0	Sound 5 with AM/FM, single-disc CD, MP3
F61	Rearview mirror
F66	Lockable glove compartment
FF5	Shelf above windshield
FJ1	Hinged lid for center console storage compartment
HH2	Electric heater booster
HH9	Air conditioning, front compartment
HZ9	Diesel heater booster - 5kW
J10	Speedometer, km/h
J65	Outside temperature display
L65	Interior lights, cargo/passenger compartment
S04	Adjustable passenger's seat
S22	Armrest for driver's seat
S25	Armrest for front passenger's seat
T74	Assist handle at sliding door on B-pillar
T85	Assist handle, left rear door
T86	Assist handle, right rear door
V43	Wood floor
V85	Smoker's package, front console
VH5	LIMA Cloth seats

EXTERIOR

D03	High roof
F68	Heated and power adjustable side mirrors
H21	Heat-insulating glass with windshield band
L05	Automatic daytime running lights
L94	Deletion of parking lamps
LB5	LED brake light
MZ0	BlueEFFICIENCY badge
P47	Front mud flaps
P48	Rear mud flaps
R65	Spare wheel bracket below frame end
R87	Spare wheel
RD9	Tire brand, unspecified
RH7	Tires - LT 215/85 R16
RM0	All-season tires
RS6	Steel wheels 5.5J x 16
RW4	Deletion of tire sealant kit
T09	Sliding door with extended track
T12	Two stage opening for sliding door
T16	Sliding door, passenger side
W54	Rear doors, double wing, 270 degree opening

SAFETY/CONVENIENCE

BB3	Electronic Stability Program (ESP)
E07	Hill-start assist
FI1	Keyless Entry
J58	Seat belt warning for driver's seat
SA5	Front airbag, driver
SA6	Front airbag, passenger
Y43	Hydraulic jack

OTHER

IG3	Tracking Code
XC8	VIN visible from outside
XS7	Labels/publications printed in English/French
XY2	Model year 2012
Z44	NAFTA vehicle registration
Z65	Packing for sea transport
ZU7	National version for Canada
ZZ4	Mercedes-Benz specification

Sprinter 3500 Cargo 170" Ext.

MY12

Ordering Designation: 35C170E Baumuster: 906 657 13

Last updated: July 12, 2011

VEHICLE PRICING & OPTIONS

Prices are valid on date of delivery. Prices, design & equipment are subject to change without notice

MSRP

Sprinter 3500 Cargo 170" Ext.

\$53,000

OPTIONAL PACKAGES

CODE	DESCRIPTION	MSRP
VPP	Convenience Package	\$500
CL4	Multifunction steering wheel w/ trip computer	
JK3	Instrument cluster with pixel-matrix display	
MS1	Cruise control	
FZ9	Two additional master keys	
VLP	Interior Lighting Package	\$300
	<i>replaces L65; not with VIP</i>	
L63	Ceiling lamp in cargo compartment	
LD0	Overhead control panel with 2 reading lamps	
VXP	Bi-xenon Headlamp Package	\$1,100
F46	Headlamp washing system	
L16	Halogen fog lamps	
LG1	Bi-xenon headlamps with cornering function	
VCP	Heated Seat Package	\$350
	<i>not with D64</i>	
H15	Heated front passenger's seat	
H16	Heated driver's seat	
VEP	Extended Cargo Package	\$700
	<i>not with D64/VFP/VIP/V46</i>	
V42	Sidewall lashing rails on waist rail	
VC4	Cargo lashing rails, upper	
VV2	Load securing rail system	
YK3	Tensioning straps	
YK4	Lashing rail straps	
VBP	Basic Window Package	\$650
	<i>not with W78/VFP/VIP</i>	
H22	Rear window defroster	
VA7	Storage compartment with net, rear doors	
W17	Fixed window, front right in sidewall/sliding door	
W61	Fixed window, rear doors	
W70	Privacy glass	
VFP	Full Window Package	\$1,300
	<i>not with W78/VA3/VEP/VBP/VHP</i>	
H22	Rear window defroster	
VA7	Storage compartment with net, rear doors	
W02	Full window package	
W16	Fixed window, front left in sidewall/sliding door	
W17	Fixed window, front right in sidewall/sliding door	
W22	Fixed window, center left	
W23	Fixed window, center right	
W27	Fixed window, rear left	
W28	Fixed window, rear right	
W61	Fixed window, rear doors	

OPTIONAL PACKAGES (Continued)

CODE	DESCRIPTION	MSRP
VMP	Mobility Prep. Package	\$790
	<i>replaces ED8+L65; not with VBP/VFP/VEP/VLP/VHP</i>	
E28	Additional battery for retrofit	
E36	Cutoff relay for additional battery	
ED5	Programmable Special Module (PSM)	
ES2	12 V Power outlet in rear compartment	
H00	Warm/cool air duct to passenger compartment	
VVP	Crew Van Package	\$2,200
	<i>not with S23/D05/VBP/VFP/VHP/VIP/VMP</i>	
H00	Warm/cool air duct to passenger compartment	
SD0	ISOFIX child seat attachment points	
U62	3-seater bench, first row, narrow	
V40	Crew cab floor assembly	
V46	Rubber floor mat in rear	
V25	Interior trim, hardboard, half height	
W16	Fixed window, front left in sidewall/sliding door	
W17	Fixed window, front right in sidewall/sliding door	
VGP	Comfort Seat Package	\$390
	<i>not with VAP/VSP</i>	
SB1	Comfort driver's seat	
SB2	Comfort passenger's seat	
VSP	Swivel Seat Package	\$950
	<i>replaces S04; not with S20/S23/S78/S91/S99/VAP/VPP</i>	
BE2	Folding handbrake lever	
S87	Driver's seat frame, low	
S88	Passenger's seat frame, low	
SB1	Comfort driver's seat	
SB2	Comfort passenger's seat	
SD2	Belt mounting point for deleted driver/passenger seat	
SR8	Swivel base for driver's seat	
SR9	Swivel base for passenger's seat	
VAP	Suspension Seat Package	\$820
	<i>replaces S04; not with D64/S23/VSP/VPP</i>	
S87	Driver's seat frame, low	
S88	Passenger's seat frame, low	
SB3	Suspension seat, comfort version, driver's seat	
SB4	Suspension seat, comfort version, passenger's seat	
VHP	Rear Heating Package	\$1,400
	<i>not with D64/V25/VIP/VFP</i>	
H01	Additional insulation for rear compartment	
H04	Additional insulation for front compartment	note: if VHP is ordered on a vehicle with D50/D51/D53, V07 must be added from individual options
H13	Additional heat exchanger	
VA3	Interior trim, washable, full height	
VIP	Luxury Interior Package	\$2,400
	<i>must have VFP; not with VA1/VA3/V25/VLP/VEP/VHP</i>	
H01	Additional insulation for rear compartment	
H04	Additional insulation for front compartment	
LD0	Overhead control panel with 2 reading lamps	
LD4	Convenience lighting in cargo/passenger compartment	
V21	Interior trim, luxury	
V31	Window pillar trim	
V36	Roof trim	
V64	Ashtrays, rear	

Sprinter 3500 Cargo 170" Ext.

MY12

Ordering Designation: 35C170E Baumuster: 906 657 13

Last updated: July 12, 2011

OPTIONAL EQUIPMENT

CODE	DESCRIPTION	MSRP
A50	Front axle, reinforced <i>must have CF6</i>	\$330
AR2	Axle ratio 3.923 <i>replaces AR3; not available until December production</i>	\$0
CF2	Suspension w/ Frt and Rr Stabilizer <i>includes:</i> C42 Rear axle stabilizer, under frame C45 Front axle stabilizer, reinforced <i>replaces C40; not with CF3/CF4</i>	\$380
CF3	Suspension w/ H.D. Rr Stabilizer <i>includes:</i> C43 Rear axle stabilizer, reinforced, under frame C45 Front axle stabilizer, reinforced <i>replaces C40; not with CF2/CF4</i>	\$360
CF4	Suspension w/ H.D. Frt and Rr Stabilizers <i>includes:</i> C42 Rear axle stabilizer, under frame C45 Front axle stabilizer, reinforced CF6 Front springs and dampers, reinforced <i>replaces C40; not with CF2/CF3/CF6</i>	\$530
CF6	Front springs and dampers, reinforced <i>must have A50; not with CF2/CF3</i>	\$0
D05	Super-high roof <i>must have FF4 if ordered with a partition</i> note: if vehicle is not arctic white, then code D06 must be ordered instead of D05	\$2,500
D13	Mounting rails for roof rack	\$250
D22	Fixed rear sunroof <i>not with VIP/H72</i>	\$540
D50	Full partition <i>includes:</i> T77 Assist handle at sliding door on partition <i>replaces D93+T74; not with D51/D53/D62/D64/VMP</i>	\$270
D51	Full partition with 1 window <i>includes:</i> T77 Assist handle at sliding door on partition <i>replaces D93+T74; not with D50/D53/D62/D64/VMP</i>	\$310
D53	Full partition with 1 sliding window <i>includes:</i> T77 Assist handle at sliding door on partition <i>replaces D93+T74; not with D50/D51/D62/D64/VMP</i>	\$490
D62	Pre-installation for partition	\$140
D64	Full partition with sliding door <i>includes:</i> T77 Assist handle at sliding door on partition S20 Folding front passenger's seat S99 Deletion of passenger's seat base <i>replaces D93+T74+S04+SA6</i> <i>not with D50/D51/D53/D62/T19/T93/VHP/VIP/VMP</i> note: passenger airbag is deleted	\$1,700
E28	Additional battery for retrofit <i>includes:</i> E36 Cutoff relay for additional battery	\$470
ED4	AGM Battery 95 Ah/850 CCA <i>replaces EE8</i>	\$190
ED5	Programmable Special Module (PSM) <i>replaces ED8</i>	\$300
EJ3	Audio 20 with AM/FM,6-disc CD, MP3, Bluetooth <i>replaces EN0; not with ER0</i>	\$900
ER0	Pre-installation for radio <i>replaces EN0; not with EJ3</i>	-\$300
ES2	12 V Power outlet in rear compartment	\$70
EZ8	PARKTRONIC	\$940
F49	Heated windshield <i>must have JA5+(VLP/VIP)</i>	\$330
FF4	Shelf above roof trim <i>must have D05</i>	\$290
FF8	Storage slot at front under roof liner - 1 DIN	\$100
FK3	Chrome grille	\$250
FR7	Rear view camera wiring prep <i>not with FR8</i>	\$80
FR8	Rear view camera <i>replaces FJ1; not with FR7</i>	\$900
FY1	Security alarm with interior motion sensor <i>must have VLP</i>	\$490
FZ9	Two additional master keys	\$140
H00	Warm/cool air duct to passenger compartment <i>not with D50/D51/D53/D64/S99</i>	\$80
H01	Additional insulation for rear compartment <i>must have V25/VA1/VA3</i>	\$140
H04	Additional insulation for front compartment <i>if ordered with D50/D51/D53 then must have V07</i>	\$140
H08	High-output A/C system in passenger compartment <i>includes:</i> V36 Roof Trim <i>must have ED4; not with VEP/VIP/VLP/VA3/D05/D22</i>	\$2,900
H12	Heater, auxiliary front 5 kW <i>replaces HZ9; not with HZ5</i>	\$250
H13	Additional heat exchanger <i>not with D64/H88/T19/T93/VC5/VVP</i>	\$940
H16	Heated driver's seat	\$210
H72	Electric roof fan <i>not with D22/H08/VIP</i>	\$480
H91	Deletion of Air-conditioning system <i>replaces HH9; not with H08</i>	-\$730
HZ5	Additional warm water heating with timer 10 kw <i>replaces HZ9; must have H13; not with H12/T19</i>	\$1,200

Sprinter 3500 Cargo 170" Ext.

MY12

Ordering Designation: 35C170E Baumuster: 906 657 13

Last updated: July 12, 2011

OPTIONAL EQUIPMENT (Continued)

CODE	DESCRIPTION	MSRP
JA5	Automatic headlamps and windshield wipers <i>must have VLP/VIP</i>	\$410
JW0	Reverse warning system <i>not with FR8</i>	\$100
L16	Halogen fog lamps	\$210
LB9	Illuminated exits	\$130
M53	High idle preset <i>includes: ED5 Programmable Special Module (PSM)</i> <i>not with MT4</i>	\$650
MD3	Speed limiter - 120 km/h	\$70
MS1	Cruise control	\$390
MT4	High idle - driver adjustable <i>includes: ED5 Programmable Special Module (PSM)</i> <i>must have ED5; not with M53</i>	\$680
N62	Pulley for additional alternator <i>not with N63</i>	\$440
N63	Pulley for additional compressor <i>not with N62</i>	\$440
Q24	Cross member with 5,000lbs towing capacity	\$250
R91	Deletion of spare wheel <i>replaces R87; must have R92+RR7</i>	-\$160
R92	Deletion of spare wheel bracket <i>replaces R65; must have R91</i>	\$0
RH0	Tire brand, Kumho	\$0
RM1	Winter tires <i>replaces RMO</i>	\$140
RR7	Tire sealant kit with electric compressor <i>replaces RW4</i>	\$30
S23	Twin front passenger seats <i>includes: S78 Assist handle for inner seat</i> <i>replaces S04+S25; not with D64/SB2/VAP/VSP/VGP</i>	\$520
SB1	Comfort driver's seat <i>not with VGP/VSP/VAP</i>	\$220
SH6	Thorax airbag, driver <i>not with SH7</i>	\$340
SH7	Thorax airbag, driver/passenger <i>not with D64/S23/SH6</i>	\$480
SH9	Window airbag, driver/passenger	\$820
T19	Sliding door, driver's side <i>not with VHP/VIP</i>	\$890
T93	Deletion of sliding door <i>replaces T09+T16; not with T19</i>	\$0
V07	Rear wall lining on back of partition <i>must have (D50/D51/D53)+H04</i>	\$340
V25	Interior trim, hardboard, half height <i>not with VA1/VA3/V21/VHP/VIP</i>	\$190
V46	Rubber floor mat in rear	\$340
V93	Deletion of wood floor <i>replaces V43</i>	-\$360
VA1	Interior trim, PVC, half height	\$410
VA3	Interior trim, washable, full height <i>not with V25/VIP/VFP/VHP</i>	\$460
VC5	Aluminum entrance panel, sliding door <i>not with H13/T19/T93/VEP/VHP</i>	\$70
VU9	Leatherette, black <i>replaces VH5; not with D64</i>	\$80
W16	Fixed window, front left in sidewall/sliding door	\$180
W17	Fixed window, front right in sidewall/sliding door	\$180
W61	Fixed window, rear doors <i>includes: H22 Rear window defroster</i> <i>VA7 Storage compartment with net, rear doors</i>	\$450
W70	Privacy glass <i>must have Wxx/VFP/VVP</i>	\$640
W73	Step for rear wall door <i>not with QA2</i>	\$180
W78	Fixed window with washer/wipers, rear doors <i>includes: H22 Rear window defroster</i> <i>VA7 Storage compartment with net, rear doors</i>	\$640
Y26	Wheel chocks	\$35
Z2D	GVWR 5,000 kg (11,030 lbs) <i>replaces XG9</i>	\$680
-	Special Paint	\$600
-	Metallic Paint	\$1,100