

**FACTORY STANDARD EQUIPMENT****POWERTRAIN/SUSPENSION**

C40	Front axle stabilizer
G40	5-speed automatic transmission (W5A 380)
K60	Straight rear-exiting exhaust
KB0	100-litre fuel tank
KL1	Auxiliary heater fuel sending unit
KL5	Fuel filter with water separator
MG5	3.0L V6 BlueTEC Diesel (OM 642 -188hp/325lb-ft)
MH1	EPA10 Compliant low-emission engine

**ELECTRONIC SYSTEMS**

E30	Battery quick-disconnect
E58	Electrics for NAFTA trailer socket
EE8	Battery, high capacity 100 Ah/760 CCA
EK1	Body builder connector under driver's seat
ES0	Jump start terminal
M46	Alternator 14 V/220 A

**INTERIOR**

CL1	Steering wheel w/ height and reach adjustment
D93	Deletion of partition
E46	12 V Power outlet in driver's seat base
EL8	Five speakers in cabin
F61	Rearview mirror
F66	Lockable glove compartment
FF5	Shelf above windshield
FJ1	Hinged lid for center console storage compartment
HH2	Electric heater booster
HH9	Air conditioning, front compartment
HZ9	Diesel heater booster - 5kW
J10	Speedometer, km/h
J65	Outside temperature display
L65	Interior lights, cargo/passenger compartment
S04	Adjustable passenger's seat
S22	Armrest for driver's seat
S25	Armrest for front passenger's seat
V85	Smoker's package, front console
VH5	LIMA Cloth seats

**EXTERIOR**

D03	High roof
H21	Heat-insulating glass with windshield band
L05	Automatic daytime running lights
L94	Deletion of parking lamps
LB5	LED brake light
MZ0	BlueEFFICIENCY badge
P47	Front mud flaps
P48	Rear mud flaps
R65	Spare wheel bracket below frame end
R87	Spare wheel
RH7	Tires - LT 215/85 R16
RM0	All-season tires
RS6	Steel wheels 5.5J x 16
RW4	Deletion of tire sealant kit
W54	Rear doors, double wing, 270 degree opening

**SAFETY/CONVENIENCE**

BB3	Electronic Stability Program (ESP)
E07	Hill-start assist
F11	Keyless Entry
J58	Seat belt warning for driver's seat
SA5	Front airbag, driver
SA6	Front airbag, passenger
Y43	Hydraulic jack

**OTHER**

IG3	Tracking Code
XC8	VIN visible from outside
XS7	Labels/publications printed in English/French
XY1	Model year 2011
Z44	NAFTA vehicle registration
Z65	Packing for sea transport
ZU7	National version for Canada
ZZ4	Mercedes-Benz specification

**STANDARD MINIBUS PACKAGE*****MINIBUS REQUIRED OPTIONS***

AR2	Axle ratio 3.923
D13	Mounting rails for roof rack
E28	Additional battery for retrofit
E36	Cutoff relay for additional battery
ED5	Programmable Special Module (PSM)
F68	Heated and power adjustable side mirrors
FK3	Chrome grille
FZ9	Two additional master keys
H22	Rear window defroster
JW0	Reverse warning system
KP2	DEF Tank, 12L, in engine compartment
MS1	Cruise control
N63	Pulley for additional compressor
P08	Covering for delivery to customer/distributor
RF1	Tire brand, Continental
RM9	Tire brand, special request
T93	Deletion of sliding door
V93	Deletion of wood floor
VA7	Storage compartment with net, rear doors
W02	Full window package
W94	Deletion of passenger compartment windows
Z2D	GVWR 5,000 kg (11,030 lbs)

**357 Commuter Shuttle**

Shuttle with front facing seating for 16 passengers and driver

*Step well lighting*

*Roof Escape Hatch*

*Rear Window Defroster*

*Rear Floor Heater*

*Main Entrance Lower Step Heater*

*AM/FM CD Player*

*LED Interior Lighting*

*Black Rubber Floor Covering*

*Rear Passenger Area Seating - Level 3 Fabric*

*Rear Passenger Area A/C*

# Sprinter Minibus

MY11

Ordering Designation: 35C170E Baumuster: 906 657 13

Last updated: July 5, 2011

## VEHICLE PRICING & OPTIONS

Prices are valid on date of delivery. Prices, design & equipment are subject to change without notice

	MSRP
<b>Sprinter MiniBus</b>	<b>\$93,200</b>

## MINIBUS OPTIONAL PACKAGES

CODE	DESCRIPTION	MSRP
350	<b>Hotel Shuttle</b> Shuttle with forward facing seating for 15 passengers and driver Commuter Shuttle Standard Equipment plus: <i>Luggage Barrier</i>	\$1,200
362	<b>Commuter - Higher Capacity Shuttle</b> Shuttle with forward facing seating for 18 passengers and driver Commuter Shuttle Standard Equipment	\$700
355	<b>Valet Shuttle</b> Shuttle with 24" briefcase rack and perimeter seating for 15 passengers and driver Commuter Shuttle Standard Equipment plus: <i>Luggage Barrier</i> <i>Luggage Rack</i>	\$1,300
351	<b>Parking Shuttle</b> Shuttle with 2 shelf 70" luggage rack and perimeter seating for 15 passengers and driver Commuter Shuttle Standard Equipment plus: <i>Luggage Rack 70"</i> <i>Carpeted kick panels with floor lighting</i>	\$900
353	<b>Airport Shuttle</b> Shuttle with 2 shelf 80" luggage rack and perimeter seating for 15 passengers and driver Commuter Shuttle Standard Equipment plus: <i>Luggage Rack 80"</i> <i>Carpeted kick panels with floor lighting</i>	\$1,400
359	<b>Paratransit Shuttle with Rear-Lift</b> Shuttle with 1 wheelchair position, 2 foldaway positions, and 10 permanent forward-facing passengers Commuter Shuttle Standard Equipment plus: <i>Rear lift (Ricon)</i> <i>1 wheelchair tie-down position</i> <i>Overhead mounted grab rail</i>	\$3,200
361	<b>Paratransit Shuttle with Side-Lift</b> Shuttle with 2 wheelchair positions, 6 foldaway positions, and 8 permanent forward-facing passengers Commuter Shuttle Standard Equipment plus: <i>Side lift (Ricon)</i> <i>2 wheelchair tie-down positions</i> <i>Overhead mounted grab rail</i>	\$8,200

# Sprinter Minibus

MY11

Ordering Designation: 35C170E Baumuster: 906 657 13

Last updated: July 5, 2011

## OPTIONAL EQUIPMENT

CODE	DESCRIPTION	MSRP
366	Keyed Exterior Door Switch	\$150
367	Two Way Radio Pre-Wire (Seat mounted)	<i>not with 455</i> \$130
371	Single 17" LCD Monitor & DVD Package	\$1,400
372	Public Announcement Interface (DVD Packages)	<i>must have 371</i> \$120
373	Public Announcement Interface (CD Player)	\$120
374	Gray Altro floor covering	<i>not with 375</i> \$600
375	Black Altro floor covering	<i>not with 374</i> \$600
377	Center Accent Stripe	\$200
378	Overhead Mounted Grab Rail	<i>not with 359/361</i> \$160
379	LED Interior Strip Lighting	\$1,900
380	LED Stepwell Lights	<i>replaces incandescent lighting</i> \$200
383	Additional Main Entrance Door Grab Handle	\$50
384	Windshield Mounted 4" x 16" Mirror	\$100
385	Interior Ad Signs	\$800
387	Commuter Shuttle Reading Lights	<i>must have 357</i> \$940
388	Paratransit Shuttle Reading Lights	<i>must have 359/361</i> \$940
389	Hotel Shuttle Reading Lights	<i>must have 350</i> \$940
399	Level 4 Passenger Seat Fabric	<i>not with 400/402/459</i> \$640
400	Level 5 Passenger Seat Fabric	<i>not with 399/402/459</i> \$820
402	Level 6 Passenger Seat Fabric	<i>not with 399/400/459</i> \$920
403	Reclining Seat Back	<i>not with 351/353/355</i> \$1,200
404	High Back Seat	<i>not with 351/353/355/410/413/459</i> \$720
405	High Line Seat	<i>not with 351/353/355/410/413/459</i> \$1,600
406	High Line Seat Arm Rest	<i>must have 405; not with 351/353/355/459</i> \$750
407	Aluminum Foot Rests	<i>not with 351/353/355</i> \$700
408	Fixed Arm Rests	<i>must have 351/353/355; not with 459</i> \$650
409	Aisle Seat Folding Arm Rests	<i>not with 351/353/355</i> \$130
410	Adjustable Headrests	<i>not with 351/353/355/404/405/459</i> \$900
411	Mesh Map Pockets on back of Passenger Seats	<i>not with 351/353/355</i> \$100
413	AV Assist Rail	<i>not with 351/353/355/404/405/459</i> \$300
414	Pillow Top Seating	<i>not with 351/353/355</i> \$480
415	Briefcase Rack	<i>deletes co-pilot seat</i> \$530
416	Sliding Aisle Seats	<i>double seats only; not with 351/353/355/459</i> \$200
417	Additional Foldaway Seat (Double 34")	<i>must have 359/361; not with 459</i> \$500
419	Fire Extinguisher - 2.5 lbs	<i>not with 420</i> \$30
420	Fire Extinguisher - 5.0 lbs	<i>not with 419</i> \$50
421	First Aid Kit	\$30
422	Seat Belt Cutter	\$30
424	Body Fluid Clean Up Kit	\$40
425	Triangle Reflector Kit	\$40
427	1 Additional Wheel Chair Position	<i>must have 359/361</i> \$500
428	2 Additional Wheel Chair Positions	<i>must have 359/361</i> \$1,000
429	1 Wheel Chair Position Storage Pouch	<i>must have 359/361</i> \$50
430	2 Wheel Chair Position, Storage Pouches	<i>must have 359/361</i> \$90
431	3 Wheel Chair Position, Storage Pouches	<i>must have 359/361</i> \$130

# Sprinter Minibus

MY11

Ordering Designation: 35C170E Baumuster: 906 657 13

Last updated: July 5, 2011

## OPTIONAL EQUIPMENT (Continued)

CODE	DESCRIPTION		MSRP
432	Braun Lift	<i>replaces Ricon Lift; must have 359</i>	\$330
433	Ricon Lift Cover	<i>must have 359/361</i>	\$310
434	Braun Lift Cover	<i>must have 432</i>	\$330
435	LED Backlit Front Destination Sign	<i>not with 436/437</i>	\$1,600
436	Horizon Destination Sign	<i>not with 435/437/438</i>	\$5,500
437	Vista Front and Side Destination Sign	<i>not with 435/436/438</i>	\$4,800
438	Vista Side Destination Sign	<i>not with 436/437</i>	\$1,700
439	Vista Programming Software & Card	<i>must have 437/438</i>	\$300
441	Horizon Programming Software & Card	<i>must have 436</i>	\$300
442	Stainless Steel Wheel Covers	<i>not with 443</i>	\$450
443	Aluminum Wheels	<i>not with 442</i>	\$1,300
444	Driver & Co-Pilot Running Boards		\$550
446	Complete Colour Change, Non-Metallic	<i>not with 447</i>	\$4,900
447	Complete Colour Change, Metallic	<i>not with 446</i>	\$5,200
451	Driver's Barrier w/ Plexiglass	<i>must have 463</i>	\$470
453	Rear Step Bumper	<i>not with 359</i>	\$470
454	Golf Rack <i>note: reduces seating capacity by 2 positions</i>	<i>must have 351/353/355</i>	\$190
455	2 Way Radio Prewire (Center Console Mounted)	<i>replaces AM/FM CD Player; not with 367</i>	\$220
456	1000 Watt Inverter w/ 6 Double Plugs		\$1,900
457	Pillow Top Head Rests	<i>must have 404; not with 351/353/355</i>	\$450
458	Cup Holders	<i>not with 351/353/355</i>	\$430
459	Luxury Seating	<i>not with 351/353/355/399/400/402/404/405/ 406/408/410/413/416/417</i>	\$3,700
460	Wheel Well Double Fold-Away Seating	<i>must have 359/361</i>	\$1,100
461	Type 1 Lap Belts with Under Seat Retractors		\$1,300
463	Driver's Barrier		\$250